



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pJXK1606054774

**1RP - 3065**

**APACHE CORP**

2/29/2016

MAR 01 2016

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED  
AUG 04 2010  
HOBBSOCD

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

DUPE

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name NM S State Battery (Nearest Well NM S State #43)	Facility Type Production Facility
Surface Owner Holt	Mineral Owner NMOCD
Lease No. 30-025-37335	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	2	22S	37E	2140'	FSL	950'	FWL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release Hydrocarbon and chlorides	Volume of Release 18	Volume Recovered 12
Source of Release Sentinel Trucking	Date and Hour of Occurrence 07/25/2010 1pm	Date and Hour of Discovery 07/25/2010 430pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Leiking	
By Whom? Natalie Gladden	Date and Hour 07/26/2010 7am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

WATER @ 35'

Describe Cause of Problem and Remedial Action Taken.\*

Truck driver fell asleep while loading his truck from the lact unit. Sentinel Trucking is taking care of the cost associated with this release but Apache is doing the remediation. Standing fluid was vacuumed up immediately and excavation of saturated soil was dug out immediately as well.

Describe Area Affected and Cleanup Action Taken.\*

The contaminated soil will be hauled to Sundance Disposal once the NMOCD Standards for chlorides/TPH have been met.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	Approved by District Supervisor:	
Title: EHS Environmental Tech	Approval Date:	Expiration Date:
E-mail Address: <a href="mailto:natalie.gladden@apachecorp.com">natalie.gladden@apachecorp.com</a>	Conditions of Approval:	
Date: 07/25/2010 Phone: 575-390-4186	Attached <input type="checkbox"/> RRP-06-14-3065	

\* Attach Additional Sheets If Necessary