



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1606056684

1RP - 3071

APACHE CORP

2/29/2016

MAR 01 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

AUG 16 2012

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name NEDU #238	Facility Type Producing well

Surface Owner McNeil Ranch	Mineral Owner State of NM	API No. 30-025-35403
----------------------------	---------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
S	2	21S	37E	2500	FSL	1700	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/Produced Water	Volume of Release 20	Volume Recovered 15
Source of Release BPV	Date and Hour of Occurrence 06/27/12	Date and Hour of Discovery 06/27/12
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Natalie Gladden	Date and Hour 06/27/12 5:27pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW=27'



Describe Cause of Problem and Remedial Action Taken.*

Trash was found in the back pressure valve which caused the stuffing box to blow out.

Describe Area Affected and Cleanup Action Taken.*

BPV was cleaned out and stuffing box packing was repacked. Remediation will follow the NMOCD Guidelines to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by Environmental Specialist:  Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: 07/01/12	Expiration Date: 09/01/12
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 09/01/12	Attached <input type="checkbox"/> IRP-06-14-3071
Date: 07/01/12 Phone: 575-390-4186		

* Attach Additional Sheets If Necessary