



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pGRL1136133369

**1RP - 2772**

**LINN ENERGY HOLDINGS, LLC**

3/8/2016

MAR 08 2016





LINW CMU #38



LINE CMU #38




W-3 Road





25x  
O  
18  
2012





**Leking, Geoffrey R, EMNRD**

---

**From:** VonGonten, Glenn, EMNRD  
**Sent:** Friday, January 27, 2012 9:12 AM  
**To:** Leking, Geoffrey R, EMNRD  
**Cc:** Sanchez, Daniel J., EMNRD  
**Subject:** RE: Linn Caprock Maljamar #38

**HOBBS OCD**

**JAN 27 2012**

Geoff,

**RECEIVED**

Please tell them to submit a revised C-141 noting the probably impact to ground water to you and copy me. When they get definitive data from the analyses of the ground water they should also submit that to you and to me. Santa Fe will then call in a Remediation Plan pursuant to Part 29 to delineate the ground water impact. After that, we will decided on a ground water remediation plan.

Glenn

---

**From:** Leking, Geoffrey R, EMNRD  
**Sent:** Friday, January 27, 2012 7:23 AM  
**To:** VonGonten, Glenn, EMNRD  
**Subject:** Linn Caprock Maljamar #38

Glenn


This email follows up on the voice mail that I left yesterday afternoon. The 1RP for the site on the webpage is 2772. Linn performed a boring to 146 feet bgs where they encountered ground water. The sample at 145' displayed chlorides at a concentration of 1760 ppm. Linn would like to know the path forward administratively and technically. Thank you.

Geoff

W-3 Road



Tank Battery and Well  
Site



Center SP


1A SP

EXCAVATE

2A SP

Fiberglass line

PROPOSED MONITORING  
WELL LOCATION



WINK 575-390-3477

**Job/Location: Caprock Maljamar Unit # 38**

**Date:** \*1/25/12

[illegible][illegible]



## HUNGRY HORSE LLC

DAILY COST FOR JAN. 25, 2012

CMU #38

### DRILL RIG USAGE FOR DELINEATION

#### DRILL RIG

DRILL SAMPLE POINT 2A	50' @ 33.00/FT	\$1650.00
SUPPORT TRUCK		\$ 161.50
ENVIRONMENTAL SUPERVISOR		\$424.00
VEHICLE MILEAGE		\$262.00
FIELD TEST FOR CHLORIDES		\$80.00

---

TOTAL	\$2577.50
Cum. Cost	\$10,344