

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

MAR 30 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit report to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1609150946

OPERATOR

X Initial Report Final Report

Name of Company <i>Lime Rock Resources II-A, L.P. 277558</i>	Contact Mike Barrett
Address R347-2 North 26 Street, Artesia, New Mexico 88210	Telephone No. 505-353-2644
Facility Name Atoka San Andres Unit No. 141	

Surface Owner Fee	Mineral Owner State	API No. 30-015-10550
-------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	13	18S	26E	2310'	FSL	2310'	FEL	EDDY

Latitude 32.74685 Longitude 104.33441

NATURE OF RELEASE


Type of Release Produced waters	Volume of Release 15 bbls	Volume Recovered 10 bbls
Source of Release injection line	Date and Hour of Occurrence 3/26/2016 10:30am	Date and Hour of Discovery 3/26/2016 10:30am
Was Immediate Notice Given? Yes No X Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A line located near the wellhead at WIW well developed a pinhole size leak, the line was immediately shut-in, and the line was repaired. A vacuum truck was immediately brought to the facility, standing fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*
The affected area is located on location and in farm land south of the WIW well. This area was measured to be 10'-30' W x 175' L. R.T. Hicks Consultants has been contracted for the corrective actions on release. Work Plan: The impacted material from the release will be excavated and transported to and NMOCD approved Land Fill for disposal. Conformation soil samples will be collected upon completion of excavation. Like material will be utilized to backfill the excavated area.
Site Ranking: Depth to ground water <50', Wellhead protection Area->1000', Distance to Surface Water Body>1000'. Total Ranking score: 20.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

AMENDED	OIL CONSERVATION DIVISION	
Signature: 	Approved by Environmental Specialist: 	
Printed Name: Michael Barrett	Approval Date: <u>3/31/16</u>	Expiration Date: <u>NA</u>
Title: Production Superintendent	Conditions of Approval: Attached <input type="checkbox"/>	
E-mail Address: Michael Barrett <mbarrett@limerockresources.com>	Remediation per O.C.D. Rules & Guidelines	
Date: 3/30/2016 Phone: 505-353-2644	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 5/11/2016 *2RP-3627*

Bratcher, Mike, EMNRD

From: Mike Stubblefield <mike@rthicksconsult.com>
Sent: Wednesday, March 30, 2016 9:00 PM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD; 'Michael Barrett'; jsmith@limerockresources.com; 'Randall Hicks'
Subject: Initial C-141 with Remediation plan for the Lime Rock Resources II-A, L.P. Atoka San Andres Unit No.141 release
Attachments: Executed C-141 (3).pdf

Dear Mr. Mike Bratcher and Ms. Heather Patterson,

R.T. Hicks Consultants is sending the initial C-141 form for the Atoka San Andres Unit No.141 release, the Remediation plan is also contained with-in this form. Excavation actions will begin on 3/31/16, NMOCD will be notified to witness confirmation soil samples collected when the excavation actions are concluded. A hard copy for the Atoka San Andres Unit No.141 release will also be hand delivered to the NMOCD Artesia office. Please contact me if further information is required.

Sincerely,

Mike Stubblefield
R.T. Hicks Consultants