

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

FAB1610237309
NAB1610237475

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company-Cimarex Energy <i>215099</i>	Contact- James Tinney	
Address-600 N Marienfeld Ste 600, Midland Tx 79701	Telephone No. 575 706 0095	
Facility Name-Red Lake Disposal Line (pipeline)	Facility Type- Disposal Line	
Surface Owner	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County - Eddy
	22	17S	28E					

Latitude- 32-48'-5" 32.8014 Longitude- 104-4'-34" 104.0761 - *Conversion*

NATURE OF RELEASE

workplan lists 32.815055N 104.167486W

Type of Release- Produce Water	Volume of Release- 80-100 bbls	Volume Recovered-5 bbls
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Message was left for Mike Bratcher @ NMOCD	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
JUL 23 2012

Describe Cause of Problem and Remedial Action Take: Disposal line leaked locked out pumps at battery. Vacuum truck picked up water at spot of bad line. Cut and repaired disposal line.

NMOCD ARTESIA
VACUUM TRUCK PICKED UP WATER
at spot of bad

Describe Area Affected and Cleanup Action Take: impacted area is 300' to the east and 75' to the south. Called out vac truck to pick up standing water. Notified Talon to sample and start clean up plan

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James Tinney</i>	OIL CONSERVATION DIVISION	
Printed Name: James Tinney	Approved by District Supervisor:-	
Title: Production Foreman	Approval Date: <i>4/11/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: jtinney@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-22-12 Phone: 575-706-0095	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *5/11/16*

2RP-1295

* Attach Additional Sheets If Necessary