District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

MAR 09 2011 HOBBSOCD Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Santa Fe, NM 87505 HOBBST Release Notification and Corrective Action

Oil Conservation Division

1220 South St. Francis Dr.

						OPERA	TOR	[Initia	al Report	\bowtie	Final I
Name of Co	mpany: P	ride Energy	Company		-	Contact: M	atthew L. Pride					
Address: P	O. BOX	701950, TU	LSA, OK	74170-1950	1	Telephone 1	No. 918-524-92	200				
Facility Nar							e: Oil Well					
Surface Ow	ner: Peard	ce Trust		Mineral (Owner:	: Fee Lease No						
				LOC	ATION	OF REI	FASE					
Unit Letter	Section	Township	Range	Feet from the	_	South Line	Feet from the	East/We	est Line	County		
В	24	118	33E	660	No	orth	2310	East]	LEA	
			Lat	itude		Longitud	le					
				NAT	TURE	OF REL	EASE					
ype of Rele	ase Water	and very little	oil	11/2 8.3	CICL		Release Approx	. 5 bbls.	Volume	e Recovered	d Appr	ox. 5 bb
Source of Re						Date and Ho	our of Occurrence A			d Hour of Dis		
Was Immedia	ate Notice (Given?				8/20/08 If VES To	Whom? OCD (N	Javev Bro	own) (see	comments	helow)	
rus Immedi	ate i totice (Yes 🗌	No Not R	equired	11 120, 10	whom. ocb (ii	nately Div	(see	Comments	octow)	
By Whom?	See comme	nts below				Date and I	lour					-
Was a Water		ched?					olume Impacting	the Water	course.			
			Yes 🛛	No								
Describe Cau Drilling rig to		em and Reme	dial Action	Taken.*								
Maxey Brow	n, field insp		NMOCD, i			/08. Area Eas	st of drilling pit w	as affecte	d; contam	inated soil	was ren	moved &
regulations all oublic health should their out or the environ	or the envi operations h ment. In a	are required t ronment. The nave failed to	o report an acceptance adequately OCD accept	d/or file certain in e of a C-141 repo investigate and in	release no ort by the remediate	otifications as a NMOCD m a contaminati	knowledge and und perform correct arked as "Final R on that pose a three the operator of	ctive actio eport" do reat to gro	ns for rele es not reli und water	eases which eve the ope , surface wa	may er erator of ater, hu	ndanger f liability man hea
Signature:	n	rack	u L	Prioce	0		OIL CON	SERVA	ATION	DIVISIO	<u>N</u>	
Printed Name	By: P	ride Producti General Part	ion Co., In	ic.		Approved by	District Supervis	or:				
Title:	By:	Matthew L. e: President	Pride			Approval Dat	te:	E	xpiration	Date:		
E-mail Addre		pride-energy	.com			Conditions of	f Approval:			Attached		
Date: 3/7/		ets If Necess		Phone:918-524-9	200							



New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governe

Brett F. Woods, PH.D Acting Cabinet Secretary Daniel Sanchez Acting Division Director Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program

Trevering the Integrity of One Environment

17-Feb-11

PRIDE ENERGY COMPANY P.O. BOX 701602 TULSA OK 74170-1602

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

INBE 24 No	.001			B-24-11S-33E	30-025-38084-00-	00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/16/2011	Routine/Periodic	Maxey Brown	Yes	No	3/22/2011	iMGB110475825
	Violations					
	Emergency/Temporary I	fits				
Comments		ng Pit Open. NEED TO REM				

Oil Conservation Division
1625 N. French Drive • Hobbs, New Mexico 88240
Phone (575) 393-6161 • Fax (575) 393-0720 • www.emnrd.state.nm.us/OCD

MANGER, OCD-DISTRICT | 575-393-6161, EXT 114. MGB.



In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By;" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

Hobbs OCD District Office


COMPLIANCE OFFICER

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.


"Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

Oil Conservation Division 1625 N. French Drive • Hobbs, New Mexico 88240 Phone (575) 393-6161 • Fax (575) 393-0720 • www.emnrd.state.nm.us/OCD





INBE 24 #1 30-025-38084



2/16/2011

PRIDE ENERGY COMPANY

(918) 524-9200 • Fax (918) 524-9292 • www.pride-energy.com

Physical Address:

4641 E 91st. Street Tulsa, OK 74137

Mailing Address:

P.O. Box 701950 Tulsa, OK 74170-1950 mattp@pride-energy.com

Email Address:

Via Certified Mail Return Receipt #

New Mexico Energy, Minerals, and Natural Resources Department

Oil Conservation Division

1625 N. French Drive

Hobbs, NM 88240

February 21, 2011

91 7108 2133 3938 8584 0711

Attn: Maxey Brown

RE: Inbe 24 No. 001

API No. 30-025-38084

Section 24-11S-33E: NW 1/4 NW 1/4 (Unit Letter B)

Lea County, New Mexico

Dear Mr. Brown.

In reference to the above described well and NMOCD's letter dated February 17, 2011 (copy attached), please find enclosed a copy of Pride Energy Company's letters to the New Mexico Oil Conservation Division (NMOCD) dated September 10, 2008, August 5, 2008, and May 23, 2008, requesting approval from the NMOCD to close the drilling pit. Pride Energy Company is ready to close the above referenced drilling pit, however we await NMOCD approval of the closure plans submitted with the C-144 Form.

Thank you, and if there are any questions, please feel free to contact me at (918) 524-9200.

Sincerely,

Pride Energy Company

Matthew L. Pride

Matthew L. Pride

mp12051.kh

PRIDE ENERGY COMPANY

(918) 524-9200 + Fax (918) 524-9292 + www.pride-energy.com

Physical Address:

Kensington Tower 2250 East 73rd Street, Suite 550 Tulsa, OK 74136

Mailing Address: Email Address: P.O. Box 701950 Tulsa, OK 74170-1950 mattp@pride-energy.com

September 10, 2008

New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division 1625 N.French Drive Hobbs, NM 88240 Via Certified Mail Return Receipt # 91 3408 2133 3931 4291 4048

ATTN: Larry Johnson

RE:

Inbe 24 #1

API#: 30-025-38084

Section 24-11S-33E: 660' FNL and 2,310' FEL

Lea County, New Mexico

Dear Larry

In reference to the above described well, please find attached a Form C-144 (with original signature) requesting approval to close the pit. This form was sent to the NMOCD on May 23, 2008, but must have gotten lost.

Thank you Larry, and if there are any questions, please feel free to contact me at 918-524-9200.

Sincerely.

mattlen L. Pria

Matthew L. Pride Pride Energy Company

Page 1 of 1

mp10803.ca

Matthew Pride

From:

Matthew Pride

Sent: To: Tuesday, August 05, 2008 5:18 PM

MaxeyG Brown@state.nm.us FW: Inbe 24 #1, Section 24-11S-33E, Lea County, NM

Subject: Attachments:

Inbe 24 #1 52308.pdf

Maxey,

In reference to the above described well and your letter dated July 30, 2008, we are having a roustabout crew to fix the fence. We had the fluids removed from the drilling pit after drilling was completed, but we will be re-checking the pit and will remove any rain water that may have accumulated since.

Attached is Pit Closure Plan, Form C-144 that was e-mailed to the NMOCD on May 23, 2008. We have been waiting for approval by the NMOCD of this Form before continuing with the pit closure.

Thanks Maxey, and if there are any questions, please feel free to contact me at (918)524-9200.

Matthew L. Pride Pride Energy Company P.O. Box 701950 Tulsa, OK 74170 (918) 524-9200 (918) 524-9292 Fax

From: Matthew Pride

Sent: Friday, May 23, 2008 11:18 AM
To: Larry Johnson (larry.johnson@state.nm.us)
Cc: Cindy Herrera (Cindy.Herrera@state.nm.us)

Subject: Inbe 24 #1, Section 24-11S-33E, Lea County, NM

Larry,

In reference to the above described well, attached is Form C-144.

Thanks Larry, and if there are any questions, please feel free to contact me at (918)524-9200.

Matt Pride Pride Energy Company

1


District 1 1625 N. French Dr. Hobbs, NM 88240 District III 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Rond, Artec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505


State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-144 June 1, 2004 For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒

Type of action: Registration of a pit of	or below-grade tank 🗵 Closure of a pit or below-	grade tank			
Operator Pride Energy Company Telephone	(918)524-9200 e-mail address	mattp@pride-energy.com			
Address: PO Box 701950 Tulsa, OK 74170-1950					
Facility or well made. INBE 24 #1APL4;30-025-38084					
County: Lea Latitude	e 33 21 24 1 Longitude 103 33 58 8	NAD: 1927 🗌 1983 🖾			
Surface Owner: Federal State Private Indian					
Pit	Below-grade tank				
Type: Drilling S Production Disposal D	Volume:bbl Type of fluid:				
Workover	Construction material Double-walled, with leak detection? Yes If not, explain why not.				
Lined Unlined					
Liner type: Synthetic M Thickness 12 mil Clay					
Pit Volume 14366bb					
Depth to ground water (vertical distance from bottom of pit to seasonal	Less than 50 feet	(20 points) xxx see attached map			
high water elevation of ground water . See attached maps	50 feet or more, but less than :00 feet	(10 points)			
riigii water eleviinisi to ground water i see anached major	100 feet or more	(0 points)			
	Yes	(20 points)			
Wellhead protection area: (Less than 200 feet from a private domestic	No	(0 points) xx see attached map			
water source, or less than 1000 feet from all other water sources.)	744	(o prints) to see anatorica simp			
Distance to suffer a many those annual distance to all undistance along	Less than 200 feet	(20 points)			
Distance to surface water (horizontal distance to all wetlands, playas,	200 feet or more, but less than 1000 feet	(10 points)			
irrigation canals, ditches, and perennial and ephemeral watercourses.)	1000 feet or more	(0 points)			
	Ranking Score (Total Points)	20 points			
If this is a pit closure: (1) Attach a diagram of the facility showing the pit	s relationship to other equipment and tanks. (2) In	dicate disposal location: (check the onsite box if			
your are burying in place) onsite offsite If offsite, name of facility		The state of the s			
remediation start date and end date. (4) Groundwater encountered. No []					
		it, and attach sample results.			
(5) Attach soil sample results and a diagram of sample locations and excava-	tions.				
Additional Comments:					
All pit material will be excavated and exported the material					
we will test the soils beneath the pit in accordance with the	mandates set forth in the new Pit Rule (1	19.15.17.13.B.(1).b.1) If additional			
work is necessary after excavation, we will identify the wor	k in a closure plan. A closure report or	closure plan will include a site diagram.			
I hereby certify that the information above is true and complete to the best has been/will be constructed or closed according to NMOCD guideline	of my knowledge and belief. I further certify the	at the above-described pit or below-grade tank			
By Pride Production Co. Inc.	es a general permit in an (anacaca) and	THE COLD REPORTED PRINCES			
Date 5/23/08 Title: General Partner	Signature Matthew	1 20 100			
By: Matthew L. Pride	Signature	L. TARCE			
Your ecrtification and NMCXT) approval of this application/closure does		ents of the pit or tank contaminate ground water or			
Your certification and NAVE, It applies a of this application constraints of otherwise endanger public health or the environment. Not does it relieve regulations.	the operator of its responsibility for compliance wi	th any other federal, state, or local laws and/or			
Approvat		5			
Printed Name/Title	Signature	Date:			





Any 2003

Matthew Pride

From:

Matthew Pride

Sent:

Friday, May 23, 2008 11:18 AM

To: Cc: Larry Johnson (larry.johnson@state.nm.us)
Cindy Herrera (Cindy.Herrera@state.nm.us)
Inbe 24 #1, Section 24-11S-33E, Lea County, NM
Inbe 24 #1 52308.pdf

Subject: Attachments:

Larry,

In reference to the above described well, attached is Form C-144.

Thanks Larry, and if there are any questions, please feel free to contact me at (918)524-9200.

Matt Pride Pride Energy Company P.O. Box 701950 Tulsa, OK 74170 (918)524-9200


District I 1625 N. French Dr., Hobbs, NM 88240 District III 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Britzos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-144 June 1, 2004 For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒

Type of action: Registration of a pit of	or below-grade tank 🔯 Closure of a pit or below-gra	de tank
Operator. Pride Energy Company Telephone	e-mail address:	mattp@pride-energy.com
Address: _PO Box 701950 Tulsa, OK 74170-1950		
Facility or well name: INBE 24 #1API #:30-025-38084	U/L or Qtr/Qtr B Sec 24 T 11	S R 33E 660 FNL 2310 FEL
County: Lea Latitude	e 33 21 24.1Longitude 103 33 58.8	NAD: 1927 ☐ 1983 ⊠
Surface Owner: Federal 🔲 State 🗀 Private 🔯 Indian 🗀		
Pir Type; Drilling \(\text{Production} \) Disposal \(\text{Workover} \) Emergency \(\text{Lined} \text{ Unlined} \) Liner type: Synthetic \(\text{Thickness} \) 12 mil Clay \(\text{Clay} \)	Below-grade tank Volume:bbl Type of fluid Construction material: Double-walled, with leak detection? Yes If not	
Pit Volume 14366bbl		I as a second
Depth to ground water (vertical distance from hottom of pit to seasonal high water clevation of ground water.) See attached maps.	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) xxx see attached map (10 points) (0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points) xx see attached map
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, sitches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points)
	Ranking Score (Total Points)	20 points
If this is a pit clusure; (1) Attach a diagram of the facility showing the pit's your are burying in place) onsite ☐ offsite ☑ If offsite, name of facility_remediation start date and end date. (4) Groundwater encountered. No ☐ V (5) Attach soil sample results and a diagram of sample locations and excavations.	Gandy Mariey (3) Attach a gener	al description of remedial action taken including
Additional Comments		
All pit material will be excavated and exported the material we will test the soils beneath the pit in accordance with the		
work is necessary after excavation, we will identify the wor		
work is necessary and excavation, we will becauty the wor	a in a crosure plan. A crosure report of cro	sure plan with meridee a site single-
I hereby certify that the information above is true and complete to the best has been/will be constructed or closed according to NMOCD guideline. By: Pride Production Co., Inc. Title: General Partner By: Matthew L. Pride Title: President Your certification and NMOCD approval of this application/closure does otherwise endanger public health or the environment. Nor does it relieve regulations.	s [], a general permit [], or an (attached) alterna Signature	tive OCD-approved plan L. Paiolo of the pit or tank contaminate ground water or
Approval: Printed Name/Title	Signature	Date:



May 2008

P.O. Box 701950 Tulsa, OK 74170 (918)524-9200 District.1
1625 N. French Dr., Hobbs, NM 88240
District.11
1301 W. Grand Avenue, Artesia, NM 88210
District.11
1000 Rio Brazos Roud, Aztec, NM 87410
District.1V
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.


For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure


Is pit or below-grade tank covered by a "general plan"? Yes \(\subseteq \text{No} \text{No} \)

If partial Registration of a put or below-grade tank \(\overline{\text{No}} \) Closure of a pit or below-grade tank

Address: PO Box 701950 Tulsa, OK 74170-1950	e: (918)524-9200 e-mail address	-			
Facility or well name: INBE 24#1 API#. 30-025-38084	U/L or Ou/Our B Sec 24 T	11S R 33E 660 ENI 2310 EEI			
County Lea Latitud					
Surface Owner Federal State Private Indian	Longhade 103 33 38 8	NAD. 1927 🗀 1965 🖂			
Pit	Below-grade tank				
Type: Drilling M Production Disposal D	Volume:bbl Type of fluid				
Workover Emergency	Construction material:				
Lined Chinaed	Double-walled, with leak detection? Yes If not, explain why not				
Liner type: Synthetic Thickness 12 mil Clay Clay □					
Pit Volume 14366bbl					
	Less than 50 feet	(20 points) xxx see attached map			
Depth to ground water (vertical distance from bottom of pit to seasonal	50 feet or more, but less than 100 feet	(10 points)			
high water elevation of ground water.) See attached maps	100 feet or more	(0 points)			
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)			
water source, or less than 1000 feet from all other water sources.)	No	(0 points) xx see attached map			
and some or less than 1500 feet from all evid waser sources.	Less than 200 feet	(20 m /m)			
Distance to surface water. Thorizontal distance to all wetlands, playas,	200 feet or more, but less than 1000 feet	(20 points) (10 points)			
irrigation canals, ditches, and perennul and ephemeral watercourses.)	1000 feet or more	(0 points)			
	170007,70007,70007	(o points)			
	Bauling Sagra (Tatal Boints)	20 points			
	Ranking Score (Total Points)	20 points			
If this is a pit closure: (1) Attach a diagram of the facility showing the pit	's relationship to other equipment and tanks. (2) Ir	ndicate disposal location (check the onsite box if			
our are burying in place) onsite 🔲 offsite 🖾 If offsite, name of facility	s relationship to other equipment and tanks. (2) Ir Gundy Marley (3) Attach a ge	ndicate disposal location (check the onsite box if thereal description of remedial action taken including			
our are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered: No	s relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gr Yes If yes, show depth below ground surface	ndicate disposal location (check the onsite box if thereal description of remedial action taken including			
our are burying in place) onsite [] offsite [] If offsite, name of facility_ emediation start date and end date. (4) Groundwater encountered. No [] 5) Attach soil sample results and a diagram of sample locations and excava	s relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gr Yes If yes, show depth below ground surface	ndicate disposal location (check the onsite box if thereal description of remedial action taken including			
our are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered. No 51 Attach soil sample results and a diagram of sample locations and excava Additional Comments:	's relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gr Yes If If yes, show depth below ground surface thous	ndicate disposal location" (check the onsite boy if crieral description of remedial action taken including the and attach sample results			
cour are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered. No 5: Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material	's relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gi Yes [1] If yes, show depth below ground surface_ titions. to the Gandy Marley Landfill. After ex	indicate disposal location: (check the onsite boy if check the onsite boy if c			
cour are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered. No Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils beneath the pit in accordance with the	s relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gi Yes If yes, show depth below ground surface_ ittons. to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (the disposal location (check the onsite boy if check t			
cour are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered. No 5: Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material	s relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gi Yes If yes, show depth below ground surface_ ittons. to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (the disposal location (check the onsite boy if check t			
cour are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered. No Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils beneath the pit in accordance with the	s relationship to other equipment and tanks. (2) Ir Gandy Merley (3) Attach a gi Yes If yes, show depth below ground surface_ ittons. to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (the disposal location (check the onsite boy if check t			
cour are burying in place) onsite offsite If offsite, name of facility_ emediation start date and end date. (4) Groundwater encountered: No 5: Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils beneath the pit in accordance with the work is necessary after excavation, we will identify the wor Thereby certify that the information above is true and complete to the best has been/will be constructed or closed according to NMOCD guideling.	s relationship to other equipment and tanks. (2) Ir Gandy Marley (3) Attach a gr Yes [1] If yes, show depth below ground surface attons to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (1) is in a closure plan. A closure report or of my knowledge and belief. I further certify the	the disposal location teheck the onsite boy if cherel description of remedial action taken including the and attach sample results cavation and exportation of pit material, 19.15.17.13.B.(1).b.1) If additional closure plan will include a site diagram.			
emediation start date and end date. (4) Groundwater encountered: No 5: Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils beneath the pit in accordance with the work is necessary after excavation, we will identify the work has been/will be constructed or closed according to NMOCD guideling. By: Pride Production Co., Inc.	s relationship to other equipment and tanks. (2) Ir Gandy Marley (3) Attach a gi Yes [1] If yes, show depth below ground surface attons. It to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (rk in a closure plan. A closure report or of my knowledge and belief. I further certify the es [1], a general permit [1], or an (attached) alte	indicate disposal location teheck the onsite boy if emeral description of remedial action taken including the and attach sample results cavation and exportation of pit material, 19.15.17.13.B.(1).b.1) If additional closure plan will include a site diagram.			
cour are burying in place) onsite offsite If offsite, name of facility emediation start date and end date. (4) Groundwater encountered: No 5: Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils heneath the pit in accordance with the work is necessary after excavation, we will identify the work Thereby certify that the information above is true and complete to the best has been/will be constructed or closed according to SMOCD guidelin By: Pride Production Co., Inc. Title: General Partner By: Matthew L. Pride	s relationship to other equipment and tanks. (2) Ir Gandy Marley (3) Attach a gi Yes [1] If yes, show depth below ground surface attons to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (rk in a closure plan. A closure report or of my knowledge and belief. I further certify the es []. a general permit []. or an (attached) alte	the disposal location teheck the onsite boy if cherel description of remedial action taken including the and attach sample results cavation and exportation of pit material, 19.15.17.13.B.(1).b.1) If additional closure plan will include a site diagram.			
emediation start date and end date. (4) Groundwater encountered: No 5) Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils beneath the pit in accordance with the work is necessary after excavation, we will identify the wor Thereby certify that the information above is true and complete to the best has been/will be constructed or chosed according to SMOCD guideline By: Pride Production Co., Inc. Date: 5/23/08 Title: General Partner	s relationship to other equipment and tanks. (2) Ir Gandy Marley (3) Attach a ge Yes [1] If yes, show depth below ground surface Ittons to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (rk in a closure plan. A closure report or of my knowledge and belief. I further certify the es [1], a general permit [1], or an (attached) alte Signature [1] Wathum not relieve the operator of liability should the control of the control	indicate disposal location 'teheck the onsite boy if cherel description of remedial action taken including the and attach sample results cavation and exportation of pit material, 19.15.17.13.B.(1).b.1) If additional closure plan will include a site diagram. at the above-described pit or below-grade tank remains OCD-approved plan			
emediation start date and end date. (4) Groundwater encountered: No 5: Attach soil sample results and a diagram of sample locations and excava Additional Comments: All pit material will be excavated and exported the material we will test the soils heneath the pit in accordance with the work is necessary after excavation, we will identify the work has been/will be constructed or closed according to NMOCD guideline By: Prides Production Co., Inc. Title: General Partner By: Maitthew L. Pride Printed Name/Title Title: President Your certification and NMOCD approval of this application/closure does officewise endanger public health or the environment. Not does it relieve to office wise endanger public health or the environment. Not does it relieve to the production of the convironment.	s relationship to other equipment and tanks. (2) Ir Gandy Marley (3) Attach a ge Yes [1] If yes, show depth below ground surface Ittons to the Gandy Marley Landfill. After ex mandates set forth in the new Pit Rule (rk in a closure plan. A closure report or of my knowledge and belief. I further certify the es [1], a general permit [1], or an (attached) alte Signature [1] Wathum not relieve the operator of liability should the control of the control	indicate disposal location (check the onsite boy if check the onsite boy if the one of th			



May 2008



May 2008

Matthew Pride

From:

Leking, Geoffrey R, EMNRD [GeoffreyR.Leking@state.nm.us]

Sent:

Friday, February 25, 2011 8:34 AM

To:

Matthew Pride

Cc:

Gonzales, Elidio L, EMNRD; Brown, Maxey G, EMNRD

Subject:

INBE 24 #1

Matt

The closure plan dated your signature 05/23/2008 appears adequate. However, there is a report of a release from the pit as documented by Maxey Brown on 08/25/2008. Please submit or resubmit the C-141 pertaining to this release. Thank you.

Geoffrey Leking Environmental Engineer NMOCD-Hobbs 1625 N. French Drive Hobbs, NM 88240

Office: (575) 393-6161 Ext. 113

Cell: (575) 399-2990

email: geoffreyr.leking@state.nm.us



NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

Governor Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

26-Aug-08

PRIDE ENERGY COMPANY

P.O. BOX 701602 TULSA OK 74170-1602

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

INBE 24 No.001

Type Inspection

Inspector

Violation?

B-24-11S-33E *Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Date 08/25/2008

Inspection

Routine/Periodic

Violations

Maxey Brown

Yes

No

11/28/2008

30-025-38084-00-00

iMGB0823859721

Surface Leaks/Spills

Comments on Inspection:

FOLLOW UP ON COMPLAINT BY RANCHER RICKY PEARCE AND FOUND A SPILL AREA EAST OF DRILLING PIT INTO PLAYA AREA. NEED TO SUBMIT C-141(RULES 116, 17) TO MR. LARRY JOHNSON HOBBS DISTRICT 1 OFFICE, FOR CLEAN UP APPROVAL FOR CLEAN UP, PRIOR TO BEGINNING WORK. THIS IS 1ST LETTER OF NON-COMPLIANCE.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

RECEIVED

MAR 09 2011 HOBBSOCD

PRIDE ENERGY COMPANY

(918) 524-9200 + Fax (918) 524-9292

Physical Address:

4641 E. 91st Street Tulsa, OK 74136 Mailing Address:

P.O. Box 701950 Tulsa, OK 74170-1950

Email Address:

mattp@pride-energy.com

March 7, 2011

New Mexico Oil Conservation 1625 N. French Drive Hobbs, NM 88240 Via Certified Mail Return Receipt #

91 7108 2133 3938 8617 7700 and E-mail: geoffreyr.leking@state.nm.us 2 Total Pages (575) 399-2990 (M)

(575) 393-6161, ext. 113

ATTN: Geoffrey R. Leking

RE:

Inbe 24 No. 001

API# 30-025-38084

Section 24-11S-33E: 660' FNL and 2310' FEL of Section (Unit Letter B)

Lea County, New Mexico

Dear Geoff,

In reference to the above well and your e-mail to me dated February 25, 2011 (copy attached), please find enclosed a completed Form C-141 (Initial and Final Report).

Thank you and if there are questions, please feel free to contact me at 918-524-9200.

Sincerely,

Matthew L. Pride

Pride Energy Company

mattle L. Pride

1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe office

Form C-144

June 1, 2004


Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒

Type of action: Registration of a pit or below-grade tank ☒ Closure of a pit or below-grade tank ☐ Operator: Pride Energy Company Telephone: (918)524-9200 e-mail address: mattp@pride-energy.com Address: PO Box 701950 Tulsa, OK 74170-1950 Facility or well name: INBE 24 #1 API #: 30-025-38084 U/L or Qtr/Qtr B Sec 24 T 11S R 33E 660 FNL 2310 FEL Latitude 33 21 24.1 Longitude 103 33 58.8 NAD: 1927 ☐ 1983 ☒ Surface Owner: Federal ☐ State ☐ Private ☒ Indian ☐ Below-grade tank Type: Drilling Production Disposal Volume: ____bbl Type of fluid: ____ Workover ☐ Emergency ☐ Construction material: Lined Unlined Double-walled, with leak detection? Yes If not, explain why not. Liner type: Synthetic

Thickness 12 mil Clay

Clay □ Pit Volume 14366 bbl Less than 50 feet (20 points) xxx see attached map Depth to ground water (vertical distance from bottom of pit to seasonal 50 feet or more, but less than 100 feet (10 points) high water elevation of ground water.) See attached maps. 100 feet or more (0 points) Ves (20 points) Wellhead protection area: (Less than 200 feet from a private domestic No (0 points) xx see attached map water source, or less than 1000 feet from all other water sources.) Less than 200 feet (20 points) Distance to surface water: (horizontal distance to all wetlands, playas, 200 feet or more, but less than 1000 feet (10 points) irrigation canals, ditches, and perennial and ephemeral watercourses.) 1000 feet or more (0 points) 20 points Ranking Score (Total Points) If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite O offsite I foffsite, name of facility Gandy Marley . (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No 🗌 Yes 🔲 If yes, show depth below ground surface _______ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. Additional Comments: All pit material will be excavated and exported the material to the Gandy Marley Landfill. After excavation and exportation of pit material, we will test the soils beneath the pit in accordance with the mandates set forth in the new Pit Rule (19.15.17.13.B.(1).b.1) If additional work is necessary after excavation, we will identify the work in a closure plan. A closure report or closure plan will include a site diagram. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan . By: Pride Production Co., Inc. 5/23/08 Title: General Partner monthew L. Pride By: Matthew L. Pride Printed Name/Title Signature Title: President Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations. Approval: Printed Name/Title Signature



District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Printed Name/Title

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒


Type of action: Registration of a pit or below-grade tank ☒ Closure of a pit or below-grade tank ☐ Operator: Pride Energy Company Telephone: (918)524-9200 e-mail address: mattp@pride-energy.com Address: PO Box 701950 Tulsa, OK 74170-1950 Facility or well name: INBE 24 #1 ____API #: 30-025-38084 ___U/L or Qtr/Qtr __ B ___Sec 24 __ T __11S __R __33E __660 FNL 2310 FEL Latitude 33 21 24.1 Longitude 103 33 58.8 NAD: 1927 ☐ 1983 ☒ Surface Owner: Federal ☐ State ☐ Private ☒ Indian ☐ Below-grade tank Type: Drilling Production Disposal Volume: ____bbl Type of fluid: ____ Workover Emergency Construction material: Lined Unlined Double-walled, with leak detection? Yes If not, explain why not. Liner type: Synthetic


Thickness 12 mil Clay

Clay □ Pit Volume 14366 bbl Less than 50 feet (20 points) xxx see attached map Depth to ground water (vertical distance from bottom of pit to seasonal 50 feet or more, but less than 100 feet (10 points) high water elevation of ground water.) See attached maps. 100 feet or more (0 points) Ves (20 points) Wellhead protection area: (Less than 200 feet from a private domestic (0 points) xx see attached map No water source, or less than 1000 feet from all other water sources.) Less than 200 feet (20 points) Distance to surface water: (horizontal distance to all wetlands, playas, 200 feet or more, but less than 1000 feet (10 points) irrigation canals, ditches, and perennial and ephemeral watercourses.) 1000 feet or more (0 points) 20 points Ranking Score (Total Points) If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite Offsite If offsite, name of facility Gandy Marley . (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No 🗆 Yes 🗀 If yes, show depth below ground surface ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. All pit material will be excavated and exported the material to the Gandy Marley Landfill. After excavation and exportation of pit material, we will test the soils beneath the pit in accordance with the mandates set forth in the new Pit Rule (19.15.17.13.B.(1).b.1) If additional work is necessary after excavation, we will identify the work in a closure plan. A closure report or closure plan will include a site diagram. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan . By: Pride Production Co., Inc. 5/23/08 Title: General Partner mothew L. Pride By: Matthew L. Pride Signature Printed Name/Title Title: President Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations. Approval:

Signature

Form C-144 June 1, 2004







NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

26-Aug-08

PRIDE ENERGY COMPANY P.O. BOX 701602 TULSA OK 74170-1602

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

INBE 24 No.001

B-24-11S-33E

30-025-38084-00-00

Inspection

Type Inspection

Inspector

*Significant

Corrective

Date

Violation?

Non-Compliance?

Action Due By:

Inspection No.

08/25/2008

Routine/Periodic

Maxey Brown

Yes

11/28/2008

iMGB0823859721

Violations

Surface Leaks/Spills

Comments on Inspection:

FOLLOW UP ON COMPLAINT BY RANCHER RICKY PEARCE AND FOUND A SPILL AREA EAST OF DRILLING PIT INTO PLAYA AREA. NEED TO SUBMIT C-141(RULES 116, 17) TO MR. LARRY JOHNSON HOBBS DISTRICT 1 OFFICE, FOR CLEAN UP APPROVAL FOR CLEAN UP, PRIOR TO BEGINNING WORK. THIS IS 1ST LETTER OF NON-COMPLIANCE.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

FIRST CLASS



017H15554612 \$0.429 08/26/2008 Mailed From 88240

US POSTAGE

PRIDE ENERGY COMPANY P.O. BOX 701602 TULSA OK 74170-1602