

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy	Contact John Osborne	
Address 2020 W. Bender Blvd. Hobbs, NM	Telephone No. 575-390-8978	
Facility Name Hallertau 5 Fed #4 H	Facility Type Temporary tanks	
Surface Owner BLM	Mineral Owner BLM	API No. 30-025-40254

LOCATION OF RELEASE

Unit Letter M	Section 5	Township 26 S	Range 32 E	Feet from the 360'	North/South Line FSL	Feet from the 660'	East/West Line FWL	County Lea
------------------	--------------	------------------	---------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude 32.078678 Longitude 103.703742

NATURE OF RELEASE

Type of Release Produced water & oil	Volume of Release 30 BBLS	Volume Recovered 10 BBLS
Source of Release Frac tanks	Date and Hour of Occurrence 3:00AM 2/4/12	Date and Hour of Discovery 4:00 AM 2/4/12
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cathy Haston / BLM	
By Whom? John Osborne	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Frac tanks ran over. Contacted Safety & Environmental Solutions, Inc. To supervise clean up and stay in contact with the BLM.

Describe Area Affected and Cleanup Action Taken.*

Fluid that made it of location is approximately 15' wide at the widest point, and 320' long. Have not started corrective action pending orders from the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: John P. Osborne	Approval Date: 4/19/12	Expiration Date: 6/19/12
Title: Production Foreman	Conditions of Approval: SUBMIT FINAL C-141 BY 6/19/12.	
E-mail Address: josborne@cimarex.com	Attached <input type="checkbox"/>	
Date: 2/6/12	Phone: 575-390-8978	4-12-2801

* Attach Additional Sheets If Necessary