

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 19 2016 Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conjunction with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NA B1620449814 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV RR 003H (PW Riser)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-37800
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 19	Township 25S	Range 30E	Feet from the 100	North/South Line	Feet from the 475	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	----------------------	------------------	----------------------	----------------	----------------

Latitude: 32.112202 Longitude: 103.912686

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 418 Barrels	Volume Recovered: 20 Barrels
Source of Release: PW pipeline	Date and Hour of Occurrence 7-16-16 @ Unknown Time	Date and Hour of Discovery 7-16-16 @ 10:33am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Shelly Tucker BLM	
By Whom? Amy Ruth	Date and Hour: 7-16-16 @ 3:59pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the 8 inch produced water pipeline due to internal corrosion releasing produced water to the ground surface. A vacuum truck was called to the location and recovered 20 barrels PW.

Describe Area Affected and Cleanup Action Taken.*

Release affected pasture along ROW. A vacuum truck was called to the location and recovered 20 barrels PW.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman		Approval Date: 7/21/16	Expiration Date: N/A
E-mail Address: bblevins@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 7-19-16 Phone: 432-214-3704		SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 8/25/16

ARP-3790

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, July 19, 2016 12:24 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly (stucker@blm.gov)
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV RR 003H (PW Riser)
Attachments: scan.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU CVX JV RR 003H (PW Riser). If you have any questions please let me know. Thanks

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Saturday, July 16, 2016 3:59 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Shelly Tucker
Cc: Blevins, Bradley
Subject: Release at PLU RR 19 Battery SWD 8" line
Attachments: image1.jpeg; ATT00001.txt; image2.jpeg; ATT00002.txt

All, This morning, BOPCO discovered an accidental release of fluids from an 8" SWD line associated with the PLU Ross Ranch 19 Battery at the coordinates within the attached photos. A C-141 will be submitted with total fluids estimated released and recovered when totals become available. Thank you.