

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUL 19 2016

Submit 1st Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

11AB1620452870

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company Devon Energy Production Company <i>6137</i>	Contact Jake Harrington, Production Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 432-214-5175	
Facility Name Cotton Draw 14 Fed Com #1H	Facility Type Oil	
Surface Owner Federal	Mineral Owner Federal	API No 30-015-42091

LOCATION OF RELEASE

Unit Letter D	Section 14	Township 25S	Range 31E	Feet from the 330	North/South Line North	Feet from the 1150	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.1367226 Longitude: -103.7535248

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 60 BBLS	Volume Recovered 45 BBLS
Source of Release Balon ball valve	Date and Hour of Occurrence 7/17/2016 @ 7:00pm	Date and Hour of Discovery 7/17/2016 @ 7:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD- Mike Bratcher BLM- Shelly Tucker	
By Whom? Hubert Perry, Night Production Foreman	Date and Hour OCD- 7/17/2016 @ 9:30pm BLM- 7/18/2016 @ 2:20pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

60 BBLS produced water was released from the Balon valve on the load line due to being left open. The valve was shut in immediately to prevent further release. All tanks returned to operation once valve was properly closed.

Describe Area Affected and Cleanup Action Taken.*

60 BBLS of produced water was released when the Balon valve on the load line was left open. All released produced water remained on Pad. The area affected was on the Western portion of the Pad. The total affected area was 20' by 75' flowing in a Westerly direction. No released fluid left location. Vacuum truck recovered approximately 45 BBLS of the released produced water. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sarah Gallegos-Troublefield</i>	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>7/21/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sarah.Gallegos-Troublefield@dmv.com	Conditions of Approval:	
Date: 7/18/2016 Phone: 575.748.1864	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>7/25/16</i>	

* Attach Additional Sheets If Necessary

2RP-3793

Patterson, Heather, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dvn.com>
Sent: Wednesday, July 20, 2016 6:58 AM
To: jamos@blm.gov; Tucker, Shelly; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Scrogum, Sandy
Subject: Cotton Draw 14 Fed Com 1H_60BBLS PW_7-17-16_Initial C-141
Attachments: Cotton Draw 14 Fed Com 1H_60 BBLS PW_7-17-16_Pic 4 of 4.JPG; Cotton Draw 14 Fed Com 1H_60 BBLS PW_7-17-16_GIS Image.pdf; Cotton Draw 14 Fed Com 1H_60 BBLS PW_7-17-16_Pic 1 of 4.JPG; Cotton Draw 14 Fed Com 1H_60 BBLS PW_7-17-16_Pic 2 of 4.JPG; Cotton Draw 14 Fed Com 1H_60 BBLS PW_7-17-16_Pic 3 of 4.JPG; Cotton Draw 14 Fed Com 1H_60 BBLS PW_7-17-16_Initial C-141.doc

Good morning,

Attached is the Initial C-141, GIS Image and 4 photo of the Cotton Draw 14 Fed Com 1H release of 60 BBLS produced water that occurred on 7/17/2016. Please be advised that the blue dot in the GIS Image represents the approximate location of the release.

Please contact me with any questions you may have.

Thank you and have a wonderful day.

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.