

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 21 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1620727724

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Breitburn	Contact	Matt Cottrell
Address	1401 McKinney St Suite 2400 Houston TX 77010	Telephone No.	432-967-7266
Facility Name	State 647 711 SWD	Facility Type	SWD
Surface Owner	COG	Mineral Owner	State of New Mexico/ Breitburn
		API No.	30-015-02055

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	27	18S	28 E	2310	South	1650	West	Eddy

Latitude 32.71950 Longitude 104.16423

NATURE OF RELEASE

Type of Release	Fire	Volume of Release	5 bbls water	Volume Recovered	None
Source of Release	Burnt Tanks	Date and Hour of Occurrence	7/8/16	Date and Hour of Discovery	7/8/16
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck the facility around 9 PM causing 2 fiber glass tanks to catch fire and burn to the ground. We got our pumper out and he shut in the wells going to this facility.

Describe Area Affected and Cleanup Action Taken.*

The affected area was contained inside the berm. We dug out 18 to 24 inches inside the berm and are in the process of rebuilding this facility. We will be sending soil samples to Cardinal lab in Hobbs New Mexico. This is a lined facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Matt Cottrell</i>		OIL CONSERVATION DIVISION	
Printed Name: Matt Cottrell		Approved by Environmental Specialist <i>[Signature]</i>	
Title: EHS Coordinator	Approval Date: 7/21/16	Expiration Date: N/A	
E-mail Address: matt.cottrell@breitburn.com	Conditions of Approval:		
Date: 7-21-2016 Phone: 432-967-7266	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 8/25/16		

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3796

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Thursday, July 21, 2016 12:46 PM
To: 'Jeanie McMillan'
Cc: Matt Cottrell; Clayton Frank; Patterson, Heather, EMNRD; Bayliss, Randolph, EMNRD
Subject: RE: c 141 for State 647 711

Looks good, and Mr. Frank called me right away this morning. Everything good on this end. Thank you all for the quick response.


Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Jeanie McMillan [mailto:Jeanie.McMillan@breitburn.com]
Sent: Thursday, July 21, 2016 11:15 AM
To: Bratcher, Mike, EMNRD
Cc: Matt Cottrell; Clayton Frank
Subject: FW: c 141 for State 647 711

Mike, attached is the completed C141 on the referenced fire. Please advise if additional information is required. I know that samples are being taken today and are being sent to be analyzed.

Thank you for your consideration in this matter. I do realize that "not knowing the rules" is not an excuse for failing to bring this to your attention.

Sincerely,
Jeanie McMillan



Jeanie McMillan-Regulatory Manager
Breitburn Operating LP, 1401 McKinney St., Suite 2400, Houston, TX 77010
Office (713) 634-4696; Cell (713) 819-4936

From: Matt Cottrell
Sent: Thursday, July 21, 2016 12:09 PM
To: Jeanie McMillan
Subject: RE: c 141 for State 647 711

Matt Cottrell
EHS Coordinator Permian
4320 SW 3001

Andrews TX 79714
Cell-432-967-7266
Office-432-523-1807
matt.cottrell@breitburn.com

From: Jeanie McMillan
Sent: Thursday, July 21, 2016 11:42 AM
To: Matt Cottrell
Subject: RE: c 141 for State 647 711

Matt, please edit this form and correct the "our" to "are" in section where you describe area affected and clean-up action taken. I am unable to edit form.

Thanks
Jeanie



Jeanie McMillan-Regulatory Manager
Breitburn Operating LP, 1401 McKinney St., Suite 2400, Houston, TX 77010
Office (713) 634-4696; Cell (713) 819-4936

From: Matt Cottrell
Sent: Thursday, July 21, 2016 11:32 AM
To: Jeanie McMillan
Cc: Clayton Frank; Cam Robbins; Martha Brock; Doug Bulman
Subject: c 141 for State 647 711

Here is the C 141 form for the state 647 711 if I can be of any further service please do not hesitate to call.

Matt Cottrell
EHS Coordinator Permian
4320 SW 3001
Andrews TX 79714
Cell-432-967-7266
Office-432-523-1807
matt.cottrell@breitburn.com