



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1620850070

1RP - 2751

CHAPARRAL ENERGY LLC

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: CHAPARRAL ENERGY LLC	Contact: Derek E. Presley	
Address: 701 CEDAR LAKE BLVD. OKLAHOMA CITY, OKLAHOMA 73114-7806	Telephone No.: (405) 426-4091 X 1491	
Facility Name: WDQSU #12 @ SAT. #1	Facility Type: INJECTION HEADER	
Surface Owner: BILL GROBE	Mineral Owner	Lease No.:

LOCATION OF RELEASE API # 30-025-12271-00-00

Unit Letter F	Section 30	Township 24S	Range 38E	Feet from the 2352	North/South Line NORTH	Feet from the 1488	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 32.18916

Longitude: -103.10335

NATURE OF RELEASE

Type of Release: PRODUCE WATER	Volume of Release: 200BBLS	Volume Recovered: 160
Source of Release: 2" VICTAULIC F/G > TO STEEL LINE	Date and Hour of Occurrence: 8-31-11	Date and Hour of Discovery: 8-31-11
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? WEE Inc. was contacted for initial investigation of site, Roy R. Rascon called Geoffery Leking for notification of leak	
By Whom? Roy R. Rascon WEE INC.	Date and Hour: unknown	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

High pressure Victaulic connection rusted over period of time, rubber seal blew out. Located source isolated and vacuumed water up and dispose of properly

Describe Area Affected and Cleanup Action Taken.*

CLEAN UP ACTION: Whole Earth Environmental Inc. has been contracted to delineate and sample site. Various samples will be sent to Cardinal Labs in Hobbs. Site will be closed in accordance to NMOCD regulations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Derek E. Presley		Approved by District Supervisor: 	
Title: Safety Specialist		Approval Date: 11/3/11	Expiration Date: 01/3/12
E-mail Address: derek.presley@chaparralenergy.com		Conditions of Approval: SUBMIT NECESSARY PAPERWORK FOR GROUND WATER INVESTIGATION WHEN	
Date: 10/30/11	Phone: (405) 426-4091 X 1491	Attached <input type="checkbox"/> IRP-11-11-2751	

* Attach Additional Sheets If Necessary

VERIFIED.