



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pJXK1621536116

**1RP - 4384**

**KEVIN O. BUTLER & ASSOCIATES, INC.**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

AUG 28 2013

RECEIVED

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

2013 AUG 28 P 2:00  
RECEIVED  
OCD

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Kevin O. Bitler & Associates, Inc.	Contact	Jimmy Reynolds
Address	P.O. Box 1171 Midland, TX 79701	Telephone No.	432-741-9484
Facility Name	Aetna Eaves	Facility Type	Salt Water Disposal
Surface Owner	Valetta Ruth Fingado	Mineral Owner	
		API No.	30-025-27789

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	26	16S	38E	990	South	660	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE


Type of Release	Salt Water	Volume of Release	250	Volume Recovered	250
Source of Release	Off Setting Lease	Date and Hour of Occurrence	8/20/13	Date and Hour of Discovery	8/20/13
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	State Electrical Inspector	Date and Hour 8/20/13			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* We were waiting on Electrical Inspector due to lightening striking one of our meters when Texland sent water while there was no electricity.

Describe Area Affected and Cleanup Action Taken.\* affected area is within the tank battery. We picked up all water using three vacuum trucks. A backhoe is to be here today to pick up all contaminated dirt, store it on 30 mil plastic on location to be disposed of properly and contaminated dirt will be replaced with clean dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Lisa Builta	Approved by Environmental Specialist:		
Title: Compliance/Regulatory Compliance	Approval Date:	Expiration Date:	
E-mail Address: lisab@kobutler.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8/21/2013	Phone: 432-682-1178		

\* Attach Additional Sheets If Necessary