

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 09 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB 11622230865		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company OXY USA INC		Contact	Jennifer Duarte	
Address PO BOX 4294; HOUSTON, TX 77210		Telephone No.	713-513-6640	
Facility Name CONOCO 7 STATE #1		Facility Type	CTB	
Surface Owner		Mineral Owner	API No. 30-015-23174	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	7	19S	29E	660	SOUTH	1980	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS - FLARE	Volume of Release 200 MCF	Volume Recovered 0
Source of Release GAS - FLARE	Date and Hour of Occurrence 08/03/2016 - BEGAN	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
OXY-Dump valve on the Vertical liquid scrubber got stuck open causing gas to flare to tanks and go out flare. Stopped and repaired water dump controller.		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: JENNIFER DUARTE		Signed By:  Approved by Environmental Specialist:	
Title: ENVIRONMENTAL SPECIALIST		Approval Date: 8/9/16	Expiration Date: N/A
E-mail Address: jennifer_duarte@oxy.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 08/09/2016	Phone: 713-513-6640	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 9/9/16

*2RP-3545

Bratcher, Mike, EMNRD

From: Jennifer_Duarte@oxy.com
Sent: Tuesday, August 09, 2016 7:14 AM
To: Bratcher, Mike, EMNRD
Subject: CONOCO 7 STATE 1 - INITIAL- 8-3-16
Attachments: CONOCO 7 STATE 1 - INITIAL- 8-3-16.pdf

Importance: High

Mr. Bratcher,
Please find the attached initial C141 for flaring. Should you have any questions or need any additional information from me, please let me know.

Thank you,
Jennifer Duarte
Environmental Specialist
713-513-6640