



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1605036047

1RP - 2808

CROSS TIMBERS ENERGY, LLC

7/22/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised October 10, 2003

MAY 09 2012 Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Southern Union Gas Services	Contact: Rose Slade	
Address: 801 South Loop 464 Monahans, Texas 79756	Telephone No.: 817-302-9716 or 432-940-5147 (cell)	
Facility Name: Monahans Field Office	Facility Type: Natural Gas Gathering /Trunk "O" Bennett Road 5/7/12	
Surface Owner: Greg Fulfer	Mineral Owner	API No - 30-025-28822

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	31	25	37					Lea

Latitude_N32'05.432 Longitude:103'12.532

NATURE OF RELEASE

Type of Release: Crude oil, Poduced water, and Natural Gas	Volume of Release: 175 barrels	Volume Recovered: 130 barrels
Source of Release: Steel 30" Pipeline	Date and Hour of Occurrence: not known	Date and Hour of Discovery: 5/7/2012 at approximately 11:00 Am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoff Leking	
By Whom? Rose Slade	Date and Hour: 5/7/2012 at 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

GW=200'

Describe Cause of Problem and Remedial Action Taken.*



The 30" natural gas gathering line developed a leak. Repair crews arrived at the leak site and started the suface clean up of the release site and put the impacted soil onto plastic until further remediation is done at this site. The leak area was excavated and the 30" line was clamped and put back in service. The landowner was immediately notified and an environmental consultant was hired to clean and remediate the contaminated site.

Describe Area Affected and Cleanup Action Taken.*

The dimensions for the Trunk "O" Bennett Road 5-7-12 are as follows:

- 700' x 25' (Run off Area) down the road and at the release point
- The remediation of this release site is scheduled to begin on Thursday 5/10/2012

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Rose L. Slade		Approved by ENV SPECIALIST:  District Supervisor:	
Title: EHS Compliance Specialist		Approval Date: 05/08/12	Expiration Date: 07/09/12
E-mail Address: rose.slade@sug.com		Conditions of Approval: SUBMIT FINAL C-141 BY 07/09/12	
Date: 5/8/12	Phone: 432-940-5147	Attached <input type="checkbox"/> IRP-5-12-2808	

* Attach Additional Sheets If Necessary