District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr. Santa Fe, NM 87505 Across

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

					OPERA'	FOR		Initial	Report	Final Repor		
			ion Gas Serv. Ltd.	Contact					Tony Savoie			
		Box 1226 Jal, N.M. 88252		Telephone No.				505-395-2116				
Facility Name I		Lea	County Field Dept.	Facility Type				Natural Gas Gathering				
Surface Owner State		e	Mineral Owner	State Lease No.								
LOCATION OF RELEASE												
Unit Letter B	Section 12	Township 26S	Range 36E	Feet from the Nort	h/South Line	Feet from the	East/West	Line	County	Lea		
Latitude N32 03.896 Longitude W103 13.024												
NATURE OF RELEASE												
Type of Release	ase	ı	s, oil, and water	Volume of Release 651,000 Volume Recovered 230 bls Produced water, 25 bls condensate vater, 25 bls condensate								
Source of Release Pipeline					Date and Hour of Occurrence Date and Hour of 18:15 3/23/06 3/23/06 218:2					covery		
Was Immediate Notice Given? X Yes No Not Required If YES, To Whom? Gary Wink												
By Whom?					Date and Hour 3/23/06 at 18:50							
Was a Watercourse Reached? ☐ Yes ☑ No					If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.* A hole developed in the 16" pipeline and released the fluid and gas. Normal operating pressure is 25 P.S.I Sweet gas. At the time of the release the pipeline was being pigged and an estimated 2700 bls of fluid was coming into the receiver at approximately 70 P.S.I. Once the release was discovered a backhoe was dispatched to dam up and contain the fluid until the line could be blown-down.												
Describe Area Affected and Cleanup Action Taken. * Approximately 53,935 sq. ft. of caliche road and approximately 11,500 sq. ft. of pastureland was affected by the release. The heavily saturated soil was removed from the caliche road and pasture and transported to the company owned and operated land-farm. The affected area will be remediated in accordance to the NMOCD recommended guidelines on leaks and spills.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
OIL CONSERVATION DIVISION									<u>)N</u>			
Signature:				Tony Savoie								
Printed Name	e:			John A. Savoie	Approved by District Supervisor:							
Title:			EH&:	S Comp. Coord.	Approval Da	te:	Expiration			n Date:		
E-mail Addre	ess:		jasavoie@	sidrichgas.com	Conditions of Approval:			Attached				
Date: 3/27/06 Phone: 505-395-2116												
facility- inciden applica	tional She FPAC (t-nfl etion 1	ets If Necess)60933/ 106091 1006091	ary 415 33/53 2933\	09 R1D 948	-21232							