

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Name of Company <u>Apache Corp.</u>		Contact <u>HEATH A. DEAN OR BRYAN TINSLEY</u>
Address		Telephone No. <u>(505) 394-1533</u>
Facility Name <u>NEDU #414</u>		Facility Type <u>TRUNK LINE</u>
Surface Owner <u>STATE</u>	Mineral Owner <u>STATE</u>	Lease No. <u>NEDU #</u>

LOCATION OF RELEASE

Unit Letter <u>J</u>	Section <u>10</u>	Township <u>21S</u>	Range <u>37E</u>	Feet from the <u>2499</u>	North/South Line <u>S</u>	Feet from the <u>2470</u>	East/West Line <u>E</u>	County <u>Lea</u>
----------------------	-------------------	---------------------	------------------	---------------------------	---------------------------	---------------------------	-------------------------	-------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>OIL & WATER</u>	Volume of Release <u>60</u>	Volume Recovered <u>50</u>
Source of Release <u>TRUNK LINE</u>	Date and Hour of Occurrence <u>2/10/06</u>	Date and Hour of Discovery <u>2/16/06 11:00 AM</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <u>11:00 AM</u> <u>LEFT MESSAGE FOR LARRY JOHNSON</u>	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

B+H Const. Digging for Pipeline hit line. Digged out impacted soil and test, MARNEED to haul in fill.

Describe Area Affected and Cleanup Action Taken.*

Area affected was the Ditch and Digging soil out to test and haul to land fill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Heath A. Dean</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Heath A. Dean</u>		Approved by District Supervisor:	
Title: <u>Pumper</u>	Approval Date:	Expiration Date:	
E-mail Address:	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: <u>2/10/06</u>	Phone: <u>(505) 631-0125</u>		

* Attach Additional Sheets If Necessary

Incident - NPAC 0609336929
Application - PPAC 0609337182



8 ELLISON LANE, P.O. BOX 1849 EUNICE, NM 88231

TELEPHONE (505) 394-1503
FACSIMILE (505) 394-2425

406 yards of contaminated soil hauled to Sundance Services, Inc.

Manifest available on request.