

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

OCT 04 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
Return to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1617853512*

Name of Company <b>Chevron USA</b> <i>4323</i>		Contact <b>Josepha DeLeon</b>	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address <b>6301 Deauville Blvd, Midland, TX 79706</b>		Telephone No. <b>575-263-0424</b>		
Facility Name <b>Greenwood PGU #4 Battery</b>		Facility Type <b>Tank Battery</b>		
Surface Owner <b>BLM</b>	Mineral Owner	API No. <b>30-015-05616</b>		

**LOCATION OF RELEASE**

Unit Letter D	Section 27	Township 18S	Range 31E	Feet from the 600	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude **N 32.720010** Longitude **-W 103.849308**

**NATURE OF RELEASE**

Type of Release: <b>Oil</b>	Volume of Release <b>227.30 bbls</b>	Volume Recovered <b>165 bbls</b>
Source of Release: <b>Tank Bottom Failed</b>	Date and Hour of Occurrence <b>09/05/2016 @ unknown</b>	Date and Hour of Discovery <b>09/05/2016</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jaime Keyes, NMOCD Jim Amos, BLM</b>	
By Whom? <b>Josepha DeLeon</b>	Date and Hour <b>09/05/2016</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  <b>Not Applicable</b>		
Describe Cause of Problem and Remedial Action Taken.* <b>Leak from oil tank resulted in the release of contents to containment. A vacuum truck was dispatched to collect standing fluid.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>Affected area included containment area with small adjacent area outside of the berm (~0.87 bbl of oil leaked outside of the berm). A vacuum truck was called to the location and recovered 165 barrels.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Josepha DeLeon</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Josepha DeLeon</b>	Approved by Environmental Specialist <i>[Signature]</i>	
Title: <b>HES Compliance Support - Environmental</b>	Approval Date: <b>10/4/16</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>jdx@chevron.com</b>	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> <input type="checkbox"/>	
Date: <b>09/20/2016</b> Phone: <b>575-263-0424</b>	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 10/4/16

*2RP-3929*

## Bratcher, Mike, EMNRD

---

**From:** LeBlanc, Christopher S <ChristopherLeBlanc@chevron.com>  
**Sent:** Tuesday, October 04, 2016 10:33 AM  
**To:** Bratcher, Mike, EMNRD; Mathews, David [Swift]  
**Subject:** RE: Greenwood 4 CTB  
**Attachments:** Greenwood PGU 4 Battery C141.pdf

Mike,

Yes, a C-141 was turned in. See attached.

Please let me know if you need any additional information.

Thanks,

**Chris S. LeBlanc**  
Facilities Engineer

### **Chevron North America Exploration & Production Company**

*Mid-Continent Business Unit*

6301 Deauville Ave, Room N2205

Midland, TX 79707

Tel 432 687 7894

Cell 337 356 9538

[ChristopherLeBlanc@chevron.com](mailto:ChristopherLeBlanc@chevron.com)

---

**From:** Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]  
**Sent:** Tuesday, October 04, 2016 8:50 AM  
**To:** Mathews, David [Swift]  
**Cc:** LeBlanc, Christopher S  
**Subject:** [\*\*EXTERNAL\*\*] RE: Greenwood 4 CTB

David,

I have a meeting pending that I should know more on later this morning. Was a C-141 turned in for this release?

Mike Bratcher  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
O: 575-748-1283 X108  
C: 575-626-0857  
F: 575-748-9720

---

**From:** Mathews, David [Swift] [mailto:DQPO@chevron.com]  
**Sent:** Tuesday, October 04, 2016 5:52 AM  
**To:** Bratcher, Mike, EMNRD