

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 11 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1488738518 *10137* OPERATOR ☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company	Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 432-214-5175
Facility Name Ross Ranch 10 Fed 1 SWD	Facility Type Salt Water Disposal

Surface Owner Federal	Mineral Owner Federal	API No 30-05-29605
-----------------------	-----------------------	--------------------

LOCATION OF RELEASE

30-015-29605

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980'	North	660'	East	Eddy

Latitude: 32.0593872

Longitude: -103.7596054

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 211 MCF	Volume Recovered 0 MCF
Source of Release 1" poly line	Date and Hour of Occurrence October 6, 2016 @ 1:24 PM	Date and Hour of Discovery October 6, 2016 @ 1:24 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Ray Carter, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM October 10, 2016 @ 11:25 AM Mike Bratcher, OCD October 10, 2016 @ 11:28 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

The 1" poly gas line did not have a regulator on the line which allowed the pressure to build up too high causing the line to rupture leaving a 2" hole in the line. The valves were closed on the line to isolate the line and stop the release. A regulator was added to the line and part of the line has been replaced. The repaired line is back in service.

Describe Area Affected and Cleanup Action Taken.*

Approximately 211 MCF natural gas was released with 0 MCF recovered. No further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: <i>Sheila.fisher@dvn.com</i>	Approval Date: <i>10/13/16</i>	Expiration Date: <i>N/A</i>
Date: 10/11/16 Phone: 575.748.1829	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3938

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Tuesday, October 11, 2016 8:48 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Shelly Tucker (stucker@blm.gov)
Cc: Carter, Ray; Harrington, Jake; Fulks, Brett
Subject: Ross Ranch 10 Fed 1 SWD_211 MCF Air Release_10.6.16
Attachments: Ross Ranch 10 Fed 1 SWD_211 MCF Air Release_Initial & Final C-141_10.6.16.doc; Ross Ranch 10 Fed 1 SWD_211 MCF release_GIS Image_10.6.16.pdf; Ross Ranch 10 Fed 1 SWD_211 MCF release_pic 1 of 1_10.6.16.JPG

Good Morning,

Attached please find the Initial & Final C-141, GIS Image and photo for the 211 MCF natural gas release at the Ross Ranch 10 Fed 1 SWD.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.