4RP-11

District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

**Oil Conservation Division** 

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 South St. Francis Dr. Santa Fe, NM 87505

Dologoo	Notification	and	Composition	Antion
release	Tomation	anu '	Correcuve	ACHOIR

						OPERAT	OR	(	🛛 Initial	Report		Fina	Report
Name of Company OXY USA Inc.					Contact Eric Maestas								
Address770 Rosebud Rd. Amistad NM 88410					Telephone No. 575-420-7825								
Facility Name Bravo Dome Gathering System				Facility Type Carbon Dioxide Gathering System									
Surface Ow	Surface Owner Banta Mineral Owner				Banta API No. 30-059-20254								
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	-	rth/South Line Feet from the East/West Line County							
G	22	18	35	1650		North	1650	East		Union			
LatitudeN 35.767236 LongitudeW -103.202734													
NATURE OF RELEASE													
Type of Rele	Type of Release Produced Water Volume of Release 6 bbls Volume Recovered None												
Source of Re							our of Occurrence	c		Hour of Di		у	
		<u> </u>				10/10/2016 10:00 AM 10/10/2016 9:00AM							
Was Immedia	ue nouce C		Yes [	No 🖾 Not Re	ouired	If YES, To N/A	whom?						
By Whom? E	ric Maastas						our 10/10/2016 4	-00 DM					
Was a Water				· · · · · · · · · · · · · · · · · · ·			lume Impacting t		rcourse.				-
Yes 🛛 No					N/A								
If a Watercou	If a Watercourse was Impacted, Describe Fully.*N/A												
Describe Cause of Problem and Remedial Action Taken.* Produced water was spilled on the ground after a 6" steel pipeline developed a leak. There was approximately 6 bbls of produced water that ran out of the													
							ere was approxin	nately 6	bbls of pro	duced wate	er that i	ran ou	t of the
pipe onto the	pipe onto the ground. Area has been delineated in preparation for remediation.												
Describe Area Affected and Cleanup Action Taken.*													
Affected area has been delineated, Safety Environmental Solutions Inc. will be assisting with the remediation plan submittal.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION													
5.11				OIL CONSERVATION DIVISION									
Signature: The second s													
Printed Name: Eric Maestas				Approved by Environmental Specialist									
France Paris	Finned Ivame, Enc Iviaestas												
Title: HES Co	ordinator					Approval Date	10/12/16	Y	xpiration [	Date:			
E-mail Addre	steric ma	-siac@nyu rn	m			Conditions of							
Date: 10/	1116		Phone:	575-420-7825									

\* Attach Additional Sheets If Necessary

Talled to Erich. 10/13/16.000 Warding on rend. plan.

From:	Lowe, Leonard, EMNRD
To:	"Eric Maestas@oxy.com"
Cc:	Jones, William V, EMNRD
Subject:	4RP-11
Date:	Monday, October 17, 2016 9:40:00 AM
Importance:	High

Mr. Maestas,

OCD has categorized your 6 bbl release as 4RP-11. Any submitted information of this release to the OCD shall reference this 4RP-11 number.

OXY has an active environmental release that needs to be addressed and resolved.

OCD is waiting on a plan of remediation from OXY as of Friday, October 14, 2016.

## **Leonard Lowe**

Engineering Bureau Oil Conservation Division Energy Minerals and Natural Resources Department 1220 South St. Frances Santa Fe, New Mexico 87004 Office: 505-476-3492 Cell: 505-930-6717 Fax: 505-476-3462 E-mail: leonard.lowe@state.nm.us Website: http://www.emnrd.state.nm.us/ocd/