District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action	
NAB1429852113	OPERATOR
	Contact: Amy Ruth
	Telephone No. 575-887-7329 Facility Type: Exploration and Production
Surface Owner: Federal Mineral Owner: Federal API No. 30-015-31513	
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the North F 1 23S 30E 1500 North	South Line Feet from the East/West Line County 1800 West Eddy
Latitude 32.337062° Longitude -103.837058°	
NATURE OF RELEASE	
Type of Release Crude Oil and Produced Water	Volume of Release 2 bbls Oil 8 bbls PW
Source of Release Poly flow line	Date and Hour of Occurrence Date and Hour of Discovery
Was Immediate Notice Given?	10/6/2016 time unknown 10/6/2016 approx. 10 am If YES, To Whom?
Yes No Not Required	N/A
By Whom? N/A	Date and Hour N/A
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse. N/A
If a Watercourse was Impacted, Describe Fully.*	
N/A	
Describe Cause of Problem and Remedial Action Taken. Poly flow line from well ruptured in area of pasture. Pumping unit was shut down and valves were closed for repairs.	
Describe Area Affected and Cleanup Action Taken.* The leak affected approximately 8,170 square feet of pasture (most of area misted) located north of the well. Free standing fluids were recovered.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and or regulations.	
Signature:	OIL CONSERVATION DIVISION Approved by Environmental Specialist:
	Approval Date: 10/34//Le Expiration Date: N/A
	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines
Date: 10/21/2016 Phone: 432-661-0571 Attach Additional Sheets If Necessary	LATER THAN: 1 AU 10 200 AUTC

Patterson, Heather, EMNRD

From:

Ruth, Amy C. <ACRuth@BassRet.Com>

Sent:

Friday, October 21, 2016 2:35 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc:

jamos@blm.gov; Tucker, Shelly

Subject:

Initial C-141 Hudson 1 Federal 7 well 10-6-16

Attachments:

Initial C-141 Hudson 1 Federal 7 10-6-16.pdf; IMG_1769.JPG; Site Image with Leak

Area.jpg

Here is the initial C-141 for a leak that occurred in the pasture just off the north side of the Hudson 1 Federal 7 well location. FYI, there was an old reserve pit that was recapped with plastic and soil in 2014, located within the south part of the leak area over which a portion of the overspray occurred. I will confirm boundaries.



Amy C. Ruth

BOPCO, L.P.

EH&S Department

522 W. Mermod, Suite 704 Carlsbad, NM 88220 O: (575)689-3380 C: (432)661-0571