

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NOV 14 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP **Contact** Jennifer Duarte

Address PO BOX 4294; HOUSTON, TX 77210 **Telephone No.** 713-513-6640

Facility Name STATE CV COM #1 **Facility Type** WELL

Surface Owner **Mineral Owner** **API No.** 30-015-21927

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	16	20S	28E	1980	NORTH	760	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS - FLARE **Volume of Release** 157 MCF **Volume Recovered** 0

Source of Release GAS - FLARE **Date and Hour of Occurrence** 11/10/2016 - BEGAN **Date and Hour of Discovery**

Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required **If YES, To Whom?**

By Whom? **Date and Hour**

Was a Watercourse Reached? ☐ Yes ☐ No **If YES, Volume Impacting the Watercourse.**

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Flaring due to restart gas lift compressor.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Jennifer Hudson* **OIL CONSERVATION DIVISION**

Printed Name: JENNIFER HUDGENS **Signed By:** *Mike Hernandez*

Title: ENVIRONMENTAL SPECIALIST **Approval Date:** 11/22/16 **Expiration Date:** N/A

E-mail Address: jennifer_duarte@oxy.com **Conditions of Approval:** FINAL **Attached** ☒

Date: 11/14/2016 **Phone:** 713-513-6640

* Attach Additional Sheets If Necessary

*2RP-3550
FLARE
ORIG. FINAL 2/12/16

Bratcher, Mike, EMNRD

From: Jennifer_Hudgens@oxy.com
Sent: Monday, November 14, 2016 2:31 PM
To: Bratcher, Mike, EMNRD
Subject: C141s for Flaring
Attachments: Scanned from a Xerox Multifunction Device001.pdf; Scanned from a Xerox Multifunction Device002.pdf; Scanned from a Xerox Multifunction Device003.pdf

Please see the attached C141s for flaring. Should you need any additional information, please let me know.

Thank you,
Jennifer Hudgens
Environmental Specialist
713-513-6640