



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pENV000GW00036

**GW - 35**

**CONOCO INC**

4/12/2017

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Clara Cardoza
Address 1001 Arizona St	Telephone No. 505-326-9710
Facility Name San Juan Gas Plant	Facility Type Plant

Surface Owner Private	Mineral Owner	API No. N/A
-----------------------	---------------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section 14	Township 29N	Range 11W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

Latitude 36.7316 Longitude -107.9678

**NATURE OF RELEASE**

Type of Release Heat transfer media	Volume of Release unknown	Volume Recovered none
Source of Release Hot oil pump	Date and Hour of Occurrence 01/20/2017 21:00	Date and Hour of Discovery 01/20/2017 21:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith	
By Whom? Clara Cardoza	Date and Hour 01/26/2017 16:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**OIL CONS. DIV DIST. 3**

If a Watercourse was Impacted, Describe Fully.\*

**FEB 08 2017**

Describe Cause of Problem and Remedial Action Taken.\*

A bearing on a heat transfer media pump failed causing a shift in the shaft alignment. The shaft misalignment allowed a small volume of heating media to pass the pump's seal and ignite due to contact with the hot shaft. The condition was immediately detected by the plant's automated safety systems and our operator responded by taking the pump out of operation. An incipient stage fire resulted and was easily extinguished within minutes by the operator using a hand-held extinguisher and water hose. There were no injuries, spills or environmental releases.

Describe Area Affected and Cleanup Action Taken.\*

No impact to soil in the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

*Clara Cardoza*

Approved by Environmental Specialist:

*[Signature]*

Printed Name: Clara Cardoza

Title: Environmental Coordinator

Approval Date: 4/2/17

Expiration Date:

E-mail Address: clara.m.cardoza@cop.com

Conditions of Approval:

Attached ☐

Date: February 02, 2017

Phone: 505-326-9710

\* Attach Additional Sheets If Necessary

#NCS 171 0228572

①