

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 05 2017

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

PAB17A138372 Release Notification and Corrective Action

DAB17A138572

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Delaware Basin Midstream, LLC. 314437	Contact	Joe Coats
Address	231 N County Rd. 452 Orla, TX 79770	Telephone No.	432-248-3751
Facility Name	Ramsey N Residue Pipeline	Facility Type	Custody Transfer Station

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	15	26S	28E					Eddy

Latitude 32.03959 Longitude -104.07784 NAD83

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	2.475 MMSCF	Volume Recovered	None
Source of Release	Broken nipple on pipeline	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	5/26/17 @ 0913 CDT
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Scott Dawson	*7/10/17 3.3 MMSCF (per David Barry) AB	
By Whom?	Jason Zapalac	Date and Hour	Unknown *		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NA		

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

A 1/2" ball valve broke off at the threads to a Weldolet on our Ramsey N Residue Pipeline. Natural gas leak was spotted at 0913, 5/26/17 and the gas leaked until line was shut in 45 mins. later. We calculated a gas release of 2.475 MMSCF, due to vibration. Affected spool piece was removed, repairs made, and line put back in service the same day.

Describe Area Affected and Cleanup Action Taken.*

The gas was not recovered. We are currently rechecking all torque on pipeline at custody transfer station, tightening U-bolts over pipe, and installing a thrust block at receiver to reduce vibration on pipeline.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Joe Coats	Approved by Environmental Specialist Crystal Wu		
Title: HSE Representative	Approval Date: 7/10/17	Expiration Date: N/A	
E-mail Address: joe.coats@anadarko.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>	
Date: 6/1/2017	Phone: 432-248-3751		

* Attach Additional Sheets If Necessary

2RP-4289

Weaver, Crystal, EMNRD

From: Weaver, Crystal, EMNRD
Sent: Monday, June 5, 2017 8:43 AM
To: 'Joe.Coats@anadarko.com'
Cc: 'Jason.Zapalac@anadarko.com'; Bratcher, Mike, EMNRD; Oberding, Tomas, EMNRD
Subject: FW: Final Report on 5/26/17 Gas Release
Attachments: NMOCD 5.26.17 Release Report.pdf

Hello Mr. Coats,

Any releases that occur in OCD's District II jurisdiction need to be reported to myself and Mr. Bratcher. On your C-141 because you state it is a gas release only we need you to mark Initial and Final on the document.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Griswold, Jim, EMNRD
Sent: Monday, June 5, 2017 8:14 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Oberding, Tomas, EMNRD <Tomas.Oberding@state.nm.us>
Subject: FW: Final Report on 5/26/17 Gas Release

From: Dawson, Scott, EMNRD
Sent: Monday, June 5, 2017 8:04 AM
To: Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>
Subject: FW: Final Report on 5/26/17 Gas Release

FYI

SD

From: Coats, Joe [<mailto:Joe.Coats@anadarko.com>]
Sent: Monday, June 5, 2017 6:59 AM
To: Dawson, Scott, EMNRD <Scott.Dawson@state.nm.us>

Cc: Zapalac, Jason <Jason.Zapalac@anadarko.com>

Subject: Final Report on 5/26/17 Gas Release

Scott,

Please find the attached C-141 Form. If you have any further questions or concerns, please let me know.

Thanks,

Joe Coats, CSP

HSE Representative - Ramsey Gas Plant

Anadarko Petroleum Corporation

903-277-4089 (Mobile)

432-248-3751 (Office)

830-591-0211 (Home)

[Click here for Anadarko's Electronic Mail Disclaimer](#)