

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ~~(Amended)~~ ☐ Final Report

Name of Company: Range Operating New Mexico, Inc.	Contact: Linda C. Stiles	
Address: 777 Main Street Suite 800	Telephone No: (817) 810-1908.	
Facility Name: Trantula 3 Federal	Facility Type: Tank Battery	
Surface Owner: Rebecca Doom	Mineral Owner: Bureau of Land Management	Lease No: 35081


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	3	25S	37E	990	North	330	East	Lea

Latitude 32°09'39.72" N Longitude 103°08'36.67 W

NATURE OF RELEASE

Type of Release: <u>Produced Water</u>	Volume of Release 350 bbls	Volume Recovered 350 bbls
Source of Release: Load Line Nipple	Date and Hour of Occurrence 2-10-06 2:40 PM	Date and Hour of Discovery 2-10-06 2:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton NMOCD - Hobbs & John Simitz BLM - Roswell	
By Whom? Rudy Garcia	Date and Hour: 2-10-06 3:10 PM	
Was a Watercourse Reached? No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Ram Services Inc. (505) 395-3502 picking up load. Driver drove off without disconnecting hose to load line therefore breaking nipple out of tank.		
Describe Area Affected and Cleanup Action Taken.* Firewall, location & bar ditch along lease road south side of location Vacuum Truck picked up 350 bbls.. Backhoe on location smoothing dirt Crew on location repairing firewall Crew en route to repair load line.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		



Signature: <u>Linda C. Stiles</u>		OIL CONSERVATION DIVISION	
Printed Name: Linda C. Stiles		Approved by District Supervisor:	
Title: Sr. Engineering Tech	Approval Date:	Expiration Date:	
E-mail Address: lstyles@rangeresources.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 2-10-2006	Phone: (817) 810-1908		

* Attach Additional Sheets If Necessary