

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

DEC 21 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.20 NMAC

RECEIVED

NAB1736140332

Release Notification and Corrective Action

FAB1736139839

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Rover Operating LLC 371484	Contact	Kirk Faries
Address	17304 Preston RD suite 740	Telephone No.	575-513-3198
Dallas, TX 75252			
Facility Name	Delhi B State battery	Facility Type	Oil, Gas & Produced water

Surface Owner	State of New Mexico	Mineral Owner	NM State Land Office	API No.	Facility
---------------	---------------------	---------------	----------------------	---------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	28	17S	28E	330'		990'		EDDY

Latitude N 32.80032° Longitude W 104.18177°

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	10 - 20 bbls	Volume Recovered	3 - 5 bbls
Source of Release	flowline leak	Date and Hour of Occurrence	12/2/17 hour unknown	Date and Hour of Discovery	12/2/17 Approx. 10 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Happened on a Saturday, NMOCD was closed. Left messages at NMOCD for Mike Bratcher & Crystal Weaver. Also went in office 12/4/17 & signed in with Rusty Klein.			
By Whom?	Kirk Faries	Date and Hour 12/3/17 approx 10 AM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

NONE

Describe Cause of Problem and Remedial Action Taken.*

Developed small hole in flowline, spraying up into air covering weeds & mesquites with salt spray. Called out Kenamore Vacuum truck & sucked up between 3 - 5 bbls PW and hauled to disposal. Repaired flowline.

Describe Area Affected and Cleanup Action Taken.*

Salt spray over approx. 150' X 60' area in weeds & mesquites

Release will be delineated + remediated to OGD regs + COA standards

Backdrag affected area, put any contaminated soil on plastic liner (haul to land fill if hot)

Collect soil samples of affected area in proper containers, take to Cardinal Labs in Hobbs to be tested for Chloride levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Kirk Faries

Approved by Environmental Specialist

Crystal Weaver

Printed Name: Kirk Faries

Title: Production Foreman

Approval Date: 12/20/17 Expiration Date: N/A

E-mail Address: kfarries@roverpetro.com

Conditions of Approval: See Attached Attached ☒

Date: 12/4/17

Phone: 575-513-3198

* Attach Additional Sheets If Necessary

12/22/17

3RD-4536

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **12/21/17** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number 2RD-4536 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District II office in Artesia on or before 1/21/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

Weaver, Crystal, EMNRD

From: Kirk Faries <kfaries@roverpetro.com>
Sent: Thursday, December 21, 2017 10:53 AM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; Groves, Amber; Amanda Barringer
Cc: Michael Feezel; Keri Clarke; Brady Wilton; Kirk Faries
Subject: RE: Rover Operating Delhi B state flowline leak
Attachments: Artesia NM Riversideyard[1]

Crystal,
Here is the corrected C-141 on the Delhi B State leak, thanks for your help.
Thanks Kirk

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Tuesday, December 5, 2017 4:11 PM
To: Kirk Faries <kfaries@roverpetro.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Groves, Amber <agroves@slo.state.nm.us>; Amanda Barringer <abarringer@roverpetro.com>
Cc: Michael Feezel <mfeeze@roverpetro.com>; Keri Clarke <kclarke@roverpetro.com>; Brady Wilton <bwilton@roverpetro.com>; David Molina <dmolina@roverpetro.com>
Subject: RE: Rover Operating Delhi B state flowline leak

Kirk,

I have attached a version of your submitted Initial C-141 that I made some corrections to and I also made some notes for you on there on things that you need to correct before we can process this form. That disclaimer note I put on there about the "release will be delineated and remediated to OCD regs and COA," isn't anything you need to change or fix. I am just letting you know that I will be adding that on the form once you submit the corrected version of it.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Kirk Faries [mailto:kfaries@roverpetro.com]
Sent: Tuesday, December 5, 2017 12:51 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Groves, Amber <agroves@slo.state.nm.us>; Amanda Barringer <abarringer@roverpetro.com>
Cc: Michael Feezel <mfeeze@roverpetro.com>; Keri Clarke <kclarke@roverpetro.com>; Brady Wilton

<bwilton@roverpetro.com>; David Molina <dmolina@roverpetro.com>; Kirk Faries <kfaries@roverpetro.com>

Subject: Rover Operating Delhi B state flowline leak

Hi Mike, Crystal & Amber

On 12/2/17 we had a flowline leak by our Delhi B state water tank. I estimate the release of approx. 10 – 20 bbls of produced water, we immediately repaired leak and recovered close to 5 bbls and took to disposal. Went out with backhoe today 12/5/17 and removed approx. 10 yards of contaminated soil and put on plastic liner and will collect samples to send to Cardinal labs in Hobbs to test chloride levels. I have attached C-141 and will come into NMOCD artesia office to speak with Mike Bratcher on procedure. I did go to NMOCD office yesterday 12/4/17 but Mike and Crystal were not available so I signed in with Rusty Klein.

Thank you,

Kirk Faries
Production Foreman
Rover Operating LLC
575-513-3198