



2010 Afton Place
Farmington, NM 87401
Phone: (505) 278-8720
Fax: (505) 326-6112

February 15, 2018

OIL CONS. DIV DIST. 3
FEB 16 2018

Charlie Perrin
New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, New Mexico 87410

RE: Condition of Approval for Extension
Section 30 Recycling Containment and Facility #3RF-3
January 15 – February 9

CS

Dear Mr. Perrin,

Pursuant to Order R-14314, WPX submitted a C-103 for a 6-month extension request for cessation of operations on August 23, 2017, for the Section 30 Recycling Containment and Facility (#3RF-3) located in Section 30, Township 31N, Range 5W, Rio Arriba County, New Mexico. Approval of the 6-month extension was granted by Director David Catanach on August 25, 2017. Conditions of Approval (COA) of the C-103 are listed below. This report is being submitted to satisfy the monthly report requirement.

1.0 Conditions of Approval

Approval of the extension was granted with the following COA:

- 1) Take necessary actions to keep fresh water accumulation within the containment to a minimum and prevent damage from freezing.
- 2) Inspect and take photographs of the Facility weekly.
- 3) In the event of leaks of damage to the Facility, the operator must do the following.
 - a. Notify OCD District III within 72 hours of knowledge of leaks or damage.
 - b. Submit a Corrective Action Plan (CAP) to repair leaks or damage within seven days of notification above.
 - c. Upon OCD's approval of the CAP, complete repairs per the OCD-approved schedule.
- 4) By the 15th of the month, submit monthly reports to OCD District III of inspection results with photographs and progress on CAP's if any.
- 5) Verify liner integrity before returning the containment to service.

2.0 Weekly Inspections

LOGOS continues to monitor the condition of the Section 30 Recycling Containment. Attached is a summary of weekly inspections conducted at the containment from January 22-February 9. Also attached is a photograph log documenting site conditions during January 25-February 9.

3.0 Recent Event Summary

- Water in containment as of January 25, 2018. A small volume of water remains in containment due to snow melt. (See attached photograph log).
- Minimal amount of water was pumped from the leak detection over the past month.
- LOGOS personnel continue to search and inspect the liner for any potential areas of concern along the base of the containment.

6

**Section 30 Recycling Containment and Facility
February 2018 Monthly Report**

The next report will be submitted to the Aztec office by March 15, 2018. For additional information or questions regarding current site conditions, please contact me at 505-324-4145.

Sincerely,



Tamra Sessions
Regulatory Specialist

Attachments
Weekly Inspection Log Summary
Photograph Log

Section 30 Recycling Facility and Containment Inspection Summary

WEEKLY INSPECTION:

DATE:


	1/25/2018		1/29/2018		2/2/2018		2/9/2018	
	YES	NO	YES	NO	YES	NO	YES	NO
1. ARE FREEBOARD LEVELS AT 3' OR GREATER?	yes		yes		yes		yes	
2. IS THERE ANY OIL ACCUMULATION ON THE CONTAINMENT?		no		no		no		no
3. ARE THERE VISIBLE TEARS IN LINER?		no		no		no		no
4. DOES THE NET NEED MAINTENANCE?		no		no		no		no
5. IS THE FENCING IN GOOD CONDITION?	yes		yes		yes		yes	
6. HOUSEKEEPING ISSUES?		no		no		no		no
7. POND MEASUREMENT (HEIGHT)	0		0		0		0	
8. IS THERE WATER PRESENT IN THE LEAK DETECTION TUBE?	yes		yes		yes		yes	
9. DEAD WILDLIFE/BIRDS INSIDE CONTAINMENT?		no		no		no		no
COMMENTS: (include water quality, odor, color, etc.)	only water in the containment is snow melt		only water in the containment is snow melt		no water in containment		no water in containment	
ADDITIONAL OBSERVATIONS:	water will be pumped out to the SWD #1		water will be pumped out to the SWD #1. Most of the water is out.					

LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
February 2018 Monthly Report

January 25, 2018
Picture #1




January 29, 2018
Picture #2



LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
February 2018 Monthly Report

January 29, 2018
Picture #3



January 29, 2018
Picture #4



LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
February 2018 Monthly Report

February 2, 2018
Picture #5



February 9, 2018
Picture #6

