State of New Mexico **Energy Minerals and Natural Resources** 

ocd received on 2/9/18 Form C-141 Revised April 3, 2017

Submit 1 Copy to appropriate District Office in

accordance with 19.15.29 NMAC.

trict

Oil Conservation Division 1220 South St. Francis Dr.

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505													
			Rele	ease Notific	ation	and Co	orrective A	ction					
Name of Company Vanguard Operating, LLC <u>258350</u> Address 5847 San Felipe, STE 3000 Houston, TX 77057						OPERATOR Contact Jason Fisher Telephone No.505-918-0523			X Initia	al Report	Final Report		
Facility Nan	ne Tigner	State Batter	У			Facility Type Tank Battery							
Surface Ow	ner	~*~~	)wner S	State API No				. 30015313	387				
LOCATION OF RELEASE													
Unit Letter L	Section 28	Township 17S	Range 28E	Feet from the 2310	North/	South Line South	Feet from the 990	CARGO DE COMPANY	t/West Line County West Eddy				
Latitude_32.8044739_Longitude104.1861649 NAD83 NATURE OF RELEASE $\times 2 = 512$ MCF													
Type of Release Gas/Emissions									Volume Recovered 0				
Source of Release Flare						Date and Hour of Occurrence Date and Hour 2-3-2018			Hour of Dis	covery N/A			
Was Immediate Notice Given? X Yes No Not Required						If YES, To Whom? Amalia Bustamante by email							
By Whom? Chuck Johnston							Date and Hour 7:30 pm 2-3-2018						
Was a Watero	course Read	ched?		If YES, Volume Impacting the Watercourse.									
If a Watercou	rse was Im	pacted, Descr	ibe Fully."	k		·				1. 1. No.			
N/A													
Describe Cause of Problem and Remedial Action Taken.*													
Purchaser fou	ind leak on	their pipeline	and reque	sted a volume red	luction v	while making	repairs. Gas was	sent to f	lare for two	o days.			
Describe Area No impact.	a Affected a	and Cleanup A	Action Tak	ren.*									

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

n11	112	OIL CONSERVATION DIVISION					
Signature:	AU	Approved by Environmental Specialist: Accepted for very					
Title: EHS Specialist		Approval Date: 41318	Expiration D	ate:	NIA		
E-mail Address: cjohnston@vnrene	ergy.com	Conditions of Approval:		Attach	ed APO LON		
Date: 2-9-2018	Phone: 432-202-4771	tinal			OKP-TIU		

\* Attach Additional Sheets If Necessary

4/12/18AB

## Weaver, Crystal, EMNRD

From:Chuck Johnston <cjohnston@vnrenergy.com>Sent:Friday, February 9, 2018 9:25 AMTo:Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRDSubject:Weekend FlaringAttachments:2018-02-09 Flare.pdf

Crystal and Mike, please find attached the C-141's for flaring from 8 of our batteries over the weekend. Please let me know if you need anything else.

Chuck Johnston EHS / Operations Specialist 432-202-4771 Cell 432-248-8154 Office



## Bustamante, Amalia, EMNRD

From: Sent: To: Subject: Chuck Johnston <cjohnston@vnrenergy.com> Saturday, February 3, 2018 7:41 PM Bustamante, Amalia, EMNRD Flaring

Amalia, I just got word we are having to flare on a few batteries due to a pipeline leak on our purchaser's line. I will complete the C-129s when I get back to the office Tuesday. Thanks

Chuck Johnston EHS / Operations Specialist 432-202-4771 Cell 432-248-8154 Office