

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

AUG 14 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT IV ARTESIA OGD
Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1823327442

OPERATOR

X Initial Report X Final Report




Name of Company	Vanguard Operating, LLC	Contact	Jason Fisher
Address	5847 San Felipe, Ste. 3000 Houston, TX 77057	Telephone No.	505-918-0523
Facility Name	Staley State A Battery Staley State #25 Well	Facility Type	Central Battery and Well Site
Surface Owner	Mineral Owner	State	API No.30-015-41066

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	30	17S	28E	2310	South	965	East	Eddy

Latitude 32.8041649 Longitude -104.2095261 NAD83

NATURE OF RELEASE

Type of Release	Gas	Volume of Release	118 mcf	Volume Recovered	0
Source of Release	Flare	Date and Hour of Occurrence	8-10-2018	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Frontier plant went down during the lightning storm. The gas flared for 5 hours until plant was back on line.					
Describe Area Affected and Cleanup Action Taken.*					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Chuck Johnston		Signed By:  Approved by Environmental Specialist:			
Title: EHS Specialist		Approval Date: 8/20/18		Expiration Date: N/A	
E-mail Address: cjohnston@vnrenergy.com		Conditions of Approval: FINAL		Attached:  4933	
Date: 8-10-2018		Phone: 432-202-4771			

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Chuck Johnston <cjohnston@vnrenergy.com>
Sent: Tuesday, August 14, 2018 12:32 PM
To: Bratcher, Mike, EMNRD
Subject: Vanguard Operating Flaring event
Attachments: Vanguard Operating Flaring 8-10-2018.pdf

Mike, please find attached C-141 forms for flaring of gas of some of our batteries 8-10-2018. Frontier plant was knocked down during the lightning storm and we had to flare gas for 5 hours until the plant was back operational.

Let me know if you have any questions,

Chuck Johnston
EHS / Operations Specialist
432-202-4771 Cell
432-248-8154 Office

