

District I
1625 N. French Dr., Hobbs, NM 88249
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact John Abney	
Address 4001 Penbrook Street Odessa, TX 79762	Telephone No. (505)391-3128	
Facility Name State E Battery	Facility Type Oil and Gas	
Surface Owner DASCO Cattle Co.	Mineral Owner State of New Mexico	Lease No. B01536

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	17	22 South	36 East					Lea

Latitude 32 23.293N Longitude 103 16.990W

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 16 bbls	Volume Recovered 2 bbls
Source of Release Water tank overflowed	Date and Hour of Occurrence 5/13/06 07:00am	Date and Hour of Discovery 5/13/06 10:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* The water transfer pump was running but was not moving any water. It was discovered that the suction valve was closed to the pump. It is not known as to when the valve was shut and by whom. No high level alarm was received due to a failed RTU.		
Describe Area Affected and Cleanup Action Taken.* This spill consisted of approximately 2 bbls of oil and 14 bbls of produced water 0.5 bbls of oil and 1.5 bbls of water was recovered. The contaminated area is 70' X 8' within the battery and 520' X 4' of the road. No pasture land was affected by the spill. The contaminated soil will be removed and replaced with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: John Abney		Approved by District Supervisor:
Title: HSER Specialist	Approval Date:	Expiration Date:
E-mail Address: john.h.abney@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/22/2006	Phone: (505)391-3128	

Attach Additional Sheets If Necessary

facility - FPAC 0615631088
incident - FPAC 0615631174
application - FPAC 0615632461