

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Chevron U.S.A. INC	Contact Eddy Gregory
Address P.O. Drawer 29 Andrews Texas 79714	Telephone No. 432-523-7655 Ext 7603
Facility Name WDDU #88	Facility Type- Oil well

Surface Owner George Willis	Mineral Owner-Federal	Lease No.
-----------------------------	-----------------------	-----------

LOCATION OF RELEASE


API# 30025 123870000

Unit Letter	Section 5	Township 25.0S	Range 38e	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	--------------	-------------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 4.4bbl oil/95.6bbl water	Volume Recovered 0
Source of Release Production flowline	Date and Hour of Occurrence 12:00:00 5/24/06	Date and Hour of Discovery 18:00:00 5/24/06
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Sylvia Dicky	
By Whom? Eddy Gregory	Date and Hour 5/25/06 @ 16:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken Steel flow line had external corrosion causing small leak in the pipe. Shut in well and flowline, ordered replacement flowline for installation the following day.		
Describe Area Affected and Cleanup Action Taken.* 205' x 35' area was impacted by the spill. Will pick up hydrocarbon impacted soil and carry to Chevron property for road spread.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Eddy Gregory	Approved by District Supervisor:	
Title: HES Champion	Approval Date: 6-13-06	Expiration Date: 90-day
E-mail Address: eegr@chevron.com	Conditions of Approval: Report for delineation of CIG, TPH	Attached <input type="checkbox"/>
Date: 5/24/06	Phone: 432-523-3655	

* Attach Additional Sheets If Necessary

incident - nPAC 0616632139 100'
application - pPAC 0616632399
RPT# 925

BTEX