

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Armstrong Energy Corporation	Contact	Bruce Stubbs
Address	P.O. Box 1973, Roswell, NM 88202	Telephone No.	505-625-2222
Facility Name	Mobil Lea State #8 water injection pump	Facility Type	Water supply tank & Injection Pump
Surface Owner	U.S.	Mineral Owner	U.S.
		Lease No.	NM-086


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	2	20S	34E	1800	South	1980	West	Lea

100' Latitude 32.59976 N Longitude 103.53254 W

NATURE OF RELEASE

Type of Release	Produced Water & Oil	Volume of Release	5 to 10 bbls.	Volume Recovered	5 bbls.
Source of Release	Ran Tank Over	Date and Hour of Occurrence	7-13-06 AM	Date and Hour of Discovery	7-13-06 9:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Not Required	If YES, To Whom?	Gary Wink		
By Whom?	Bruce Stubbs	Date and Hour	7-13-06 Noon		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Injection Pump went down and supply water filled tank and ran it over. Called vacuum truck and sucked up fluid and used backhoe to cleanup.					
Describe Area Affected and Cleanup Action Taken.* Area around water tank and a low area behind the battery. An Area approximately 6 ft. x 50 ft. was affected. Used vacuum truck to remove fluid and backhoe to cleanup.					



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>B. Stubbs</i>	OIL CONSERVATION DIVISION		
Printed Name: Bruce Stubbs	Approved by District Supervisor:		
Title: Engineer	Approval Date:	Expiration Date:	
E-mail Address: pecos@lookingglass.net	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7-14-06	Phone: 505-625-2222		

* Attach Additional Sheets If Necessary

facility - P P A C 0 6 1 9 9 4 2 2 1 0
incident - P P A C 0 6 1 9 9 4 2 3 1 8
application - P P A C 0 6 1 9 9 4 2 9 5 7

RP# 961