

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Rice Operating Company	Contact: Jennifer Johnson	
Address: 122 West Taylor	Telephone No.: 505-393-9174	
Facility Name: Justis E-23	Facility Type: Salt Water Gathering System	
Surface Owner: Becky Doom	Mineral Owner:	Lease No.:


LOCATION OF RELEASE

Unit Letter E	Section 23	Township 24S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

94' Latitude: 32*12.430N Longitude: 103*08.513W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 barrels	Volume Recovered: N/A
Source of Release: Coupling	Date and Hour of Occurrence: N/A	Date and Hour of Discovery: 7/25/06 10:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Bolts on Coupling rusted. Replaced bolts and rubbers.		
Describe Area Affected and Cleanup Action Taken.* Approximately 1800 sq ft affected. Investigation and Characterization Plan to follow.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Johnson</i>		OIL CONSERVATION DIVISION	
Printed Name: Jennifer Johnson		Approved by District Supervisor:	
Title: Environmental and Field Technician	Approval Date:	Expiration Date:	
E-mail Address: jjohnson@riceswd.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/27/06	Phone: 505-393-9174		

* Attach Additional Sheets If Necessary

RP# 973

facility - PPAC0620835309
incident - PPAC0620835407
application - PPAC0620836476

JUSTIS E-23 DRIVING DIRECTIONS
UL/E SEC 23 T24S R37E

GPS
NAD27
32°12.430N
103°08.513W

At the intersection of HWY 18 and Cooper East Road north of Jal, turn east on Cooper East and go 2.8 miles to double cattle guards, take south (right) cattle guard and go 0.5 miles on lease road. At the "Y" in the road just prior to the caliche pit turn south and go 0.4 miles on lease road. Site is on the west side of the road across from the battery.