

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CHEVRON USA INC.	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1237 (office), 505-390-7165 (cell)
Facility Name- W.T. McComack	Facility Type - Production Battery

Surface Owner- Mrs Ilene Sims	Mineral Owner - Mrs Ilene Sims	Lease No.
-------------------------------	--------------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 32	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea

90'

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release-OIL AND PRODUCED WATER	Volume of Release 13 BO, 3 BW	Volume Recovered- 12 bbl oil and 2 bbl water
Source of Release- Pressure Relief Valve on Free Water Knock Out	Date and Hour of Occurrence- 8/11/06 5:00 am	Date and Hour of Discovery 8/11/06 @ 5:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Danny Lovell	Date and Hour 8/11/06 @ 10:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken Got called out by our H2S alarm and found that the PRV was popping off due to the pilot line was plugged off. Switched out of FWKO and sent production to heater treater.
--

Describe Area Affected and Cleanup Action Taken.* FLUID WAS CONTAINED WITHIN BATTERY YARD. STANDING FLUID WAS VACCUMED UP. DEPTH TO GW=90-100'. Will clean up hydrocarbon contaminated soil and carry to landfarm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor: 	
Title: Operations Rep	Approval Date: 8-28-06	Expiration Date: —
E-mail Address: lovld@chevrontexaco.com	Conditions of Approval: —	
Date: 8/21/06 Phone: 505-394-1237	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Facility - PPAC 0624050459
Incident - NPAC 0624050546
Application - PPAC 0624050680

RP #1017