

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Revised
Submit 2 Cop
District Of
with

Release Notification and Corrective Action

OPERATOR		Initial Report	Final Report
Name of Company John H. Hendrix, Corp.		Contact Marvin Burrows	
Address PO Box 910, Eunice NM 88231		Telephone No. 505-394-2649	
Facility Name Paddock SWD line.		Facility Type SWD line.	
Surface Owner State of NM		Mineral Owner State of NM	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	2	22 South	37 East	1880'	South	1880'	East	Lea

Latitude N 32 deg 25 min 00.8 seconds Longitude W 103 deg 08 min 18.0 sec

NATURE OF RELEASE

Type of Release Salt Water	Volume of Release Unknown	Volume Recovered No
Source of Release SWD Pipeline	Date and Hour of Occurrence 3:00 PM Aug 9, 2006	Date and Hour of Discovery 3:00 PM Aug 9, 2006
Was Immediate Notice Given? Yes	If YES, To Whom? OCD Pat Caperton via OCD answering machine.	
By Whom? Marvin Burrows	Date and Hour 4:00 PM Aug 9, 2006	
Was a Watercourse Reached? NO	If YES, Volume Impacting the Watercourse.	
If a Watercourse was impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Southern Union Gas had cut a new pipeline right of way across the pasture and nicked the top of our concrete 4 inch transit line causing it		
Describe Area Affected and Cleanup Action Taken.* Area affected was about 10' x 10'. The water rose up out of the new right of way ditch, then ran south for about 30' down a slight incline, up in a low spot beside the Southern Union right of way.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or local laws and/or regulations.		
Signature: Marvin L. Burrows		
In addition, NMOC		
d		

Facility - FPAC0627127249
incident - NPAC0627127347
application - PPAC0627127469

RP# 1045