

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Avenue, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised October 10, 2003

Submit 2 Copies to appropriate  
 District Office in accordance  
 with Rule 116 on back  
 side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

<b>Name of Company:</b> Chesapeake Energy	<b>Contact:</b> Bradley Blevins
<b>Address:</b> P.O. Box 190, Hobbs, NM 88240	<b>Telephone No.:</b> (505) 391-1462 ext. 6224
<b>Facility Name:</b> Langley Greer Oil #2	<b>Facility Type:</b> Tank Battery
<b>Surface Owner:</b> Lowell Cypert	<b>Mineral Owner:</b>
<b>Lease No.:</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	22S	36E					Lea

300'

**Latitude:** N 32° 22' 48.60" **Longitude:** W 103° 16' 38.33"

**NATURE OF RELEASE**

<b>Type of Release:</b> Brine water	<b>Volume of Release:</b> 90 bbls	<b>Volume Recovered:</b> none
<b>Source of Release:</b> Line from tank battery	<b>Date and Hour of Occurrence:</b> Unknown	<b>Date and Hour of Discovery:</b> 24 September 2006 @ 1:00 p.m.
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Larry Johnson, NMOCD	
<b>By Whom?</b> Bradley Blevins	<b>Date and Hour:</b> 26 September 2006 @ 7 am	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b> Not Applicable	

**If a Watercourse was Impacted, Describe Fully.\*** Not Applicable

**Depth to water:** ~172 bgs

**Describe Cause of Problem and Remedial Action Taken.\*** Brine water pipeline developed a leak; pipeline was shut down and pipe repaired

**Describe Area Affected and Cleanup Action Taken.\*** Approximately 2,100 square-feet of visible surface area were impacted by the release. Approximately 3-ft. of impacted soil was excavated from the release area and disposed at a State approved disposal facility. Soil borings will be advanced to delineate the vertical extent of impacted soil. Based on laboratory analytical data from soil sample collected during the advancement of the soil borings, a remediation proposal will be developed and submitted to the NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b>		<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Bradley Blevins		<b>Approved by District Supervisor:</b>	
<b>Title:</b> Field Supervisor		<b>Approval Date:</b>	<b>Expiration Date:</b>
<b>E-mail Address:</b> bblevins@chkenergy.com		<b>Conditions of Approval:</b>	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> <b>Phone:</b> (505) 391-1462 ext. 6224			

\* Attach Additional Sheets If Necessary

Facility - FPAC0627638997  
 Incident - NPAC0627639080  
 Application - pPAC0627639210

RP# 1059