

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 <sup>TH</sup> STREET	API Number 30 025 25762	Telephone No. 505.748.1471
Facility Name TENNECO APD STATE I SWD	Facility Type SWD	
Surface Owner STATE	Mineral Owner STATE	Lease No.

#### LOCATION OF RELEASE

Unit Letter P	Section 2	Township 11S	Range 34E	Feet from the 330	North/South Line SOUTH	Feet from the 990	East/West Line EAST	County LEA
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 33.38825 Longitude 103.47548

#### NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 150 B/PW	Volume Recovered 120 B/PW
Source of Release TANK	Date and Hour of Occurrence 10/10/06 3:00 PM	Date and Hour of Discovery 10/10/06 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? PAT CAPERTON	
By Whom? SHERRY BONHAM	Date and Hour 10/10/06 3:45 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

ELECTRICAL FAILURE RESULTING IN TANK OVERFLOW. ELECTRICAL POWER RESTORED.

Describe Area Affected and Cleanup Action Taken.\*

AN APPROXIMATE 100' X 35' AREA IMPACTED. ALL FLUIDS CONTAINED WITHIN BERM. VACUUM TRUCK AND CREW CALLED IN. ALL STANDING FLUIDS VACUUMED. IMMEDIATELY SCRAPPED UP IMPACTED MATERIALS AND DISPOSED AT LAND FARM. SITE EVALUATION IN PROGRESS.  
SITE RANKING: 20

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and or regulations.

#### OIL CONSERVATION DIVISION

Signature 	Approved by District Supervisor:	
Printed Name: Sherry Bonham	Approval Date: 10/23/06	Expiration Date:
Title: Environmental Regulatory Agent	Conditions of Approval: Submit state once vertical & horizontal extent found.	
E-mail Address: sherryb@ypcnm.com	Attached <input type="checkbox"/>	
Date: October 19, 2006	Phone: 505.748.1471	

incident - NPAC0629250940  
application - NPAC0629251072

RP#1098