


020
1121

XTO ENERGY
EMSU "B"
INJECTION HEADER LEAK
Near Well EMSU "B" # 906
Unit H, Section 23, T. 20 S., R. 36 E.
GPS: 32° 33' 35" N & 103° 19' 03" W

WORK PLAN



Prepared By
Eddie Seay Consulting
November 2006

incident - n PAC0632151135
application - p PAC0632151270

RP# 1121

November 13, 2006

NMOCD
ATTN: Larry Johnson
1625 N French Dr
Hobbs, NM 88240


RE: XTO Energy
EMSU "B" near well EMSU "B" # 906
Section 23, Twn. 20 S., Rng. 36 E., Unit H

Mr. Johnson:

XTO just recently had an injection leak at the header site located near well EMSU "B" # 906. We would like approval to begin cleanup as soon as possible. Attached is a copy of the work plan and C-141.

Looking forward to hearing from you.

Sincerely,

A handwritten signature in black ink, appearing to read "Eddie W. Seay". The signature is fluid and cursive, with a long, sweeping underline that extends to the right.

Eddie W. Seay, Agent
601 W. Illinois
Hobbs, NM 88242
(505) 392-2236
Seay04@leaco.net

cc: XTO Energy
Gene Hudson

WORK PLAN

General:

Leak occurred 11/10/2006, losing salt water & oil. The fluid was picked up and work began to stabilize area. Approximately 5000 sq. ft. of ground was affected.

The OCD was notified.

Groundwater:

According to State Engineer and Groundwater information, the depth of water occurs at approximately 60 feet below the surface.

Remediation Proposal:

Area was stabilized by mixing soil with fluids. Our cleanup will be to excavate contaminated soil, haul to an OCD approved facility and replace with clean soil and seed. Before backfilling, the area will be tested for TPH and chloride to assure we meet OCD guidelines, and only after OCD approves, we will backfill and level.

The OCD will be notified of all activities and a report will be filed upon completion.

Ranking Criteria Score – 10

This site has a 1000 ppm TPH cleanup and will cleanup BTEX and Chloride per OCD.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	XTO Energy	Contact	Gene Hudson
Address	Box 700 Eunew NM 87231	Telephone No.	441-1634
Facility Name	EMSU "B" Near #906	Facility Type	Injection
Surface Owner	J. Cooper	Mineral Owner	XTO
		Lease No.	

LOCATION OF RELEASE API# 3002504295000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	20	36					Lea

Latitude 32° 33' 35" Longitude 103° 19' 03"

IRP# 1121

NATURE OF RELEASE

Type of Release	Injection water same as	Volume of Release	300 bbls	Volume Recovered	200 bbls
Source of Release	Injection Header Near #906	Date and Hour of Occurrence	11/10	Date and Hour of Discovery	11/10
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Gary Wink		
By Whom?	David Paschall	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Injection line at header split. approx 300 bbls released.
Valve was shut, approx 200 bbls vacuumed up. Repaired line.

Describe Area Affected and Cleanup Action Taken.*

approximately 150 x 50 area in sand dune area. water settled
in low area. vacuumed up as much as possible. let dry & remediate per plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Eddie W Seay	Approved by District Supervisor: [Signature]	
Printed Name: Eddie W Seay	Approval Date: 11.15.06	Expiration Date: 3.15.07
Title: Agent	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: seay.04@leasos.net		
Date: 11/13/06	Phone: 392-2236	

* Attach Additional Sheets If Necessary

