

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name MCA Unit well # 386	Facility Type Oil and Gas

Surface Owner BLM	Mineral Owner BLM	Lease No API # 30-025-31100
--------------------------	--------------------------	------------------------------------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	29	17S	32E					Lea

Latitude **32.80761N** Longitude **-103.79002W**

NATURE OF RELEASE

Type of Release Produced Water W/Chlorides = ~70,000mg/L	Volume of Release 25 bbl (0 oil, 25 water)	Volume Recovered (0 oil, 0 water)
Source of Release MCA Unit well # 386 2" Injection Line	Date and Hour of Occurrence 11/15/2006 1400hrs	Date and Hour of Discovery 11/15/2006 1630hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Patricia A. Caperton NMOCD & Jim Amos BLM via email	
By Whom? Ruben Canava	Date and Hour 11/16/2006 1420hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The leak was caused by corrosion of the 2" injection line. The line will be replaced with a new line. No fluid was recoverable.

Describe Area Affected and Cleanup Action Taken.*

30'X300' of dry sandy pasture with no cows present. The spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	Approved by District Supervisor: <i>Ernie Edge</i>	
Title: HSE PSM Lead	Approval Date: 11-20-06	Expiration Date: 2-20-07
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/17/2006 Phone: 505.391.3158	<i>Submit Final C-141</i>	

• Attach Additional Sheets If Necessary

incident - n PAC063334203
application - p PAC0633334339

RPT# 1130