


RP

1193

**XTO ENERGY  
STATE N  
TANK BATTERY  
Unit F, Section 10, Tws, 17 S., Rng. 34 E.  
GPS: 32 51' 28" N & 103 33' 02" W**

**FINAL REPORT**



**Prepared By  
Eddie Seay Consulting  
March 2007**

*Clayton*  
*3/16/07*  
*PC*

March 13, 2007

NMOCD Environmental  
ATTN: Chris Williams  
1625 French Drive  
Hobbs, NM 88240

RE: XTO Energy  
State N Tank Battery  
Spill RP #1193


Mr. Williams:

XTO has completed the backfilling and leveling of the spill at the above listed battery. All excavated material was hauled to an OCD approved disposal. The clean soil was purchased from the Eidson Ranch.

This should finalize the cleanup for this site.

If you have any questions, please call.

Sincerely,



Eddie W. Seay, Agent  
Eddie Seay Consulting  
601 W. Illinois  
Hobbs, NM 88242  
(505)392-2236  
seay04@leaco.net

cc: XTO Energy  
Gene Hudson



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**  
Governor  
**Joanna Prukop**  
Cabinet Secretary

**Mark E. Fesmire, P.E.**  
Director  
**Oil Conservation Division**

3/06/2007

Eddie Seay Consulting  
On behalf of XTO Energy  
601 W. Illinois  
Hobbs, NM 88242

Re: XTO State N Tank Battery, F-10-17S-34E

Dear Eddie:

New Mexico Oil Conservation Division (OCD) personnel reviewed the closure report submitted by Eddie Seay Consulting on behalf of XTO Energy (XTO) for the site referenced above. The closure is hereby approved according to information provided.

Please be advised that OCD approval does not relieve XTO of liability should operations result in contamination of surface water, groundwater, or the environment. In addition, OCD approval does not relieve XTO of responsibility for compliance with other federal, state or local laws and or regulations.

If you have any questions or need assistance please write or call: 505-393-6161 ext. 102, or e-mail [chris.williams@state.nm.us](mailto:chris.williams@state.nm.us).

Sincerely,

*Chris Williams*  
NMOCD District1 Supervisor

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RP 1193

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	XTO Energy	Contact	Jersey Parker
Address	P.O. Box 700 Eunice, NM	Telephone No.	505-441-1628
Facility Name	State N Tank Battery	Facility Type	Tank Battery
Surface Owner	Zidson Ranch	Mineral Owner	XTO
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	17	34					Lea

Latitude 103° 33' 02" Longitude 32° 51' 28"

NATURE OF RELEASE

Type of Release	Prod - Oil	Volume of Release	566 bbl	Volume Recovered	56 bbl
Source of Release	Tank leak	Date and Hour of Occurrence		Date and Hour of Discovery	2/2/07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Caperton		
By Whom?	Jersey Parker	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Flange on tank leaked.

Describe Area Affected and Cleanup Action Taken.\*

a area 15x30 oil stained. excavated oily soil & disposed at OGD facility; New soil replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Eddie W Seay

Title: Agent

E-mail Address: seay04@lance.net

Date: 3/14/07

Phone: 505-392-2251

Approved by District Supervisor:

Approval Date: 3-15-07

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

