

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 83210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies of this Report to the appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR ☐ Initial Report ☒ Final Report

Name of Company: Targa Midstream Services L P	Contact: Tim Jordan or Cal Wrangham
Address: PO Box 1689 Lovington, NM 88260	Telephone No. (505) 396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing Plant

Surface Owner: State of New Mexico	Mineral Owner:	Lease No.
---------------------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	6	12S	34E					Lea

Latitude 33.30922N Longitude 103.54807W

NATURE OF RELEASE

Type of Release: Pipeline Leak. Natural Gas and Liquids	Volume of Release: approximately 10 barrels of liquid.	Volume Recovered: approximately 8 barrels of liquid.
Source of Release: Above ground pipeline riser valve froze and split open leaking gas and liquid	Date and Hour of Occurrence: 1/22/07	Date and Hour of Discovery Notified immediately by pumper that seen leak.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *

Above ground pipeline riser valve froze and cracked, leaking gas and liquid. Upon notification Field Operators immediately blocked in line and called vac truck to suck up freestanding liquids.

Describe Area Affected and Clear up Action Taken.*

Targa is currently scheduling Gandy Construction of Tatum, NM to dig out the area and remove any contaminated soil. The effected soil will be transported to Gandy Marley land farm. The area will be cleaned and tested per OCD Guidelines. Gandy construction removed two feet of contaminated soil down to solid rock and hauled to Gandy Land Farm. Any remaining soil will be remediated in place and new soil hauled to replace the removed soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District Supervisor: <i>[Signature]</i>	
Title: Advisor	Approval Date: <u>4-29-07</u>	Expiration Date: <u>-</u>
E-mail Address: dembrey@targa-resources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/24/07	Phone: (432) 688-0546	

Incident - n PACO 711537459

application - p PACO 711537859 ARP - 1268

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services L P	Contact: Tim Jordan or Cal Wrangham
Address: PO Box 1689 Lovington, NM 88260	Telephone No. (505) 396-3221
Facility Name: Saunders Plant	Facility Type: Gas Processing Plant

Surface Owner: State of New Mexico	Mineral Owner:	Lease No.
---------------------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	6	12S	34E					Lea

Latitude 33.30922N Longitude 103.54807W

NATURE OF RELEASE

Type of Release: Pipeline Leak. Natural Gas and Liquids	Volume of Release: approximately 10 barrels of liquid.	Volume Recovered: approximately 8 barrels of liquid.
Source of Release: Above ground pipeline riser valve froze and split open leaking gas and liquid	Date and Hour of Occurrence: 1/22/07	Date and Hour of Discovery Notified immediately by pumper that seen leak.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *


Above ground pipeline riser valve froze and cracked, leaking gas and liquid. Upon notification Field Operators immediately blocked in line and called vac truck to suck up freestanding liquids.

Describe Area Affected and Cleanup Action Taken.*

Targa is currently scheduling Gandy Construction of Tatum, NM to dig out the area and remove any contaminated soil. The effected soil will be transported to Gandy Marley land farm. The area will be cleaned and tested per OCD Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Printed Name: Cal Wrangham

Title: ES&H Specialist

E-mail Address: cwrangham@targaresources.com

Date: 1/30/07

Phone: (432) 688-0542

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

RP-1268



ARDINAL LABORATORIES

PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
TARGA
ATTN: DON EMBREY
1000 DESTA DRIVE, SUITE 3300
MIDLAND, TX 79705
FAX TO: (432) 688-0552


Receiving Date: 03/29/07
Reporting Date: 03/30/07
Project Number: NOT GIVEN
Project Name: BAGLEY
Project Location: NOT GIVEN

Sampling Date: 03/29/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: LB
Analyzed By: BC/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/Kg)	DRO (C ₁₀ -C ₂₈) (mg/Kg)	Cl* (mg/Kg)
ANALYSIS DATE		03/30/07	03/30/07	03/30/07
H12400-1	BAGLEY	28.2	1360	<16
Quality Control		777	789	490
True Value QC		800	800	500
% Recovery		97.1	98.6	98.0
Relative Percent Difference		3.3	1.1	0.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl: Std. Methods 4500-ClB

*Analysis performed on a 1:4 w:v aqueous extract.


Chemist

3/30/07
Date

H12400

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ATTN: DON EMBREY
6 DESTA DRIVE, SUITE 3300
MIDLAND, TX 79705
FAX TO: (432) 688-0552

Sampling Date: NOT GIVEN
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: BC
Analyzed By: BC/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/Kg)	DRO (>C ₁₀ -C ₂₈) (mg/Kg)	Cl* (mg/Kg)
ANALYSIS DATE		02/28/07	02/28/07	02/27/07
H12260-1	EAST BAGLEY	<10.0	1370	48
Quality Control		768	767	490
True Value QC		800	800	500
% Recovery		96.0	95.8	98.0
Relative Percent Difference		1.0	7.5	0.0

*Analysis performed on a 1:4 w/v aqueous extract.

Date _____

H12260

PLEASE NOTE: Liability and Damages. Cardinal's liability and Client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



ARDINAL LABORATORIES
101 East Marland, Hobbs, NM 88240 2111 Beechwood, Abilene, TX 79603
(505) 393-2226 FAX (505) 393-2476 (325) 673-7001 FAX (325) 673-7020

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

[illegible]



