

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Endeavor Energy	Contact: Alin Richardson
Address: 110 N. Marienfeld, Ste. 200 Midland, TX 79701	Telephone No.: (432) 848-0301
Facility Name: Terra Federal #1	Facility Type: Well location

Surface Owner: George Willis	Mineral Owner: George Willis	Lease No.: Terra Federal # 1
------------------------------	------------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter K	Section ¼ 22 SE	Township 25S	Range 37 E	Feet from the 1884'	North/South Line South	Feet from the 2175'	East/West Line West	County Lea
------------------	-----------------------	-----------------	---------------	------------------------	---------------------------	------------------------	------------------------	---------------

Latitude: 32 06'49.3" Longitude: 103 09'07.7"

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 120 BBL	Volume Recovered:
Source of Release: Valve Leak	Date and Hour of Occurrence: 3/25/2007	Date and Hour of Discovery: 3/25/2007 at 15:30.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Endeavor Energy company representative.	
By Whom? The rancher	Date and Hour: 3/25/2007 at 15:30.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Rancher's livestock tripped valve open causing 120 BBL to leak onto surrounding areas. Land owner discovered and contacted a company representative.

Describe Area Affected and Cleanup Action Taken.*

The affected area was approximately 173' x 204'. See attached dimension and depth maps. All impacted soil was excavated. Contaminated soil was placed onto temporary containment. Bottom hole samples will be collected. The soil will be blended on site and sampled to maintain levels below 100 ppm. The remediated soil will be placed back into the excavation site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Dennis Melton</u>	OIL CONSERVATION DIVISION	
Printed Name: Dennis Melton	Approved by District Supervisor: <u>ENVIR ENG</u>	
Title: Junior Project Manager	Approval Date: <u>5-11-07</u>	Expiration Date: <u>7-11-07</u>
E-mail Address: <u>bubbamelton@grandecom.net</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>4/26/2007</u> Phone: <u>(432) 561-5168</u>	<u>NOTICE OED 48 HR PRIOR TO FINAL SAMPLING</u>	

* Attach Additional Sheets If Necessary

incident - n PAC 0713431640
application - PAC 0713431734

② SUBMIT FINAL C-141 w/
DOCUMENTATION

RP#1305



