MARTIN YATES, III 1912-1985

FRANK W. YATES 1936-1986



105 SOUTH FOURTH STREET ARTESIA, NEW MEXICO 88210-2118 TELEPHONE (505) 748-1471

S P YATES CHAIRMAN EMERITUS

JOHN A. YATES CHAIRMAN OF THE BOARD

> PEYTON YATES PRESIDENT

FRANK YATES, JR. EXECUTIVE VICE PRESIDENT

JOHN A. YATES, JR. SENIOR VICE PRESIDENT

Ms. Pat Caperton NMOCD-District 1 1625 N French Drive Hobbs, NM 88240

December 18, 2006

RE: Merle State Unit 3 30-025-37545

Unit P, Section 14, T10S, R34E

Lea County, New Mexico

Dear Pat,

Enclosed, please find a Form C-141 Initial Report for the Merle State Unit 3 December 4, 2006 release date. Also included is a work plan.

Regretfully, notification of this discharge event was not given. The reason for the lack of notification was due to initial reporting from field personnel as being below the major release reporting requirements. However, when the actual report was received, the amount of the release exceeded the 25 barrel notification criteria.

Your consideration to the work plan is greatly appreciated. And should you have any questions, please don't hesitate to contact me at 505,742,4162 or sherryb@ypcnm.com. from 10 to 40 B/O

Sincerely,

Sherry Bonham

Environmental Regulatory Agent

RP 1091

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

						OP	ERATOR			Initial Report _		Final Report	
Name of Company OGRID Number YATES PETROLEUM CORPORATION 25575						Contact SHERRY BONHAM							
Address 105 S 4 TH STREET						Telephone No. 505.748.1471							
Facility Name API Number						Facility Type							
MERLE ST.		3	0-025-37545	WELL									
Surface Owr STATE	ner		Mineral Ov STATE	Lease No.									
						ON OF REI							
Unit Letter P						h/South Line TH	Feet from the 990	East/W EAST	County LEA				
			1	Latitude 33.	.44253	Longitud	e_103.42887	_1.		-			
				NA'	TUR	E OF RELI						and the second s	
Type of Rele CRUDE OIL				Volume of Release Volume Re 40 B/O 20 B/O				Recovered	ecovered				
Source of Release OIL TANKS										d Hour of Discovery 7:00 AM			
Was Immedi			No 🔲 Not Requi	If YES, To Whom? N/A									
By Whom? N/A						Date and Hour N/A							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercou N/A	ırse was İmp	acted, Describe	e Fully.*										
		m and Remedia DID NOT PICK		aken.* D. OIL TANKS R	AN O	VER.							
AN APPROX	XIMATE 25' MATERIAL		REA AFFI	i.* ECTED. VACUUI PPROVED DISPO			JP ALL STANDII	NG FLUI	DS. IMM	EDIATELY SO	CRAPI	ED UP	
all operators environment. failed to adec	are required The accepta juately invest	to report and/o ance of a C-14 tigate and reme	r file certa: I report by ediate cont	true and complete in release notificati the NMOCD mark amination that pos- ieve the operator of	ions an ked as e a thre	d perform corre "Final Report" of eat to ground was	ctive actions for re does not relieve the tter, surface water, npliance with any	eleases we operato human he other fed	hich may e r of liabilit ealth or th eral, state,	endanger public by should their of e environment. or local laws a	health perati In ad	h or the ons have dition,	
	5 1						OIL CON	NSERV	<u>a HON</u>	DIVISION			
Signature: Printed Name	Sherry Ro	nham		Approved by District Supervisor:									
		ulatory Agent		Approval Date:			Expiration Date:						
E-mail Address: sherryb@ypcnm.com						Conditions of Approval:			- Sp attor				
Date: Decer				Phone: 505.748.14	1 71					Attached	_		
Attach Addit										· · · · · · · · · · · · · · · · · · ·			

Spill Summary and Work Plan

Incident Date: December 4, 2006

Location: Merle State Unit 3

API 30-025-37545

Unit P Section 14 T10S R34E Lea County, New Mexico

The well is located approximately 14.5 miles northwest of Tatum, NM as depicted on the attached Johnson Ranch; NM USGS Quadrangle Map.

Watercourses in the area are dry except for infrequent flows in response to major precipitation events. The area, dry, clear, and windy at the time of the spill, consists of soil that is sandy loam. The bermed area and pad consists of hard packed caliche. Groundwater in the area is estimated to be at a depth of less than 50 feet according to the Chevron/Texaco Lea County Depth to Groundwater Trend Map.

The ranking for this site is twenty (20) based on the following:

Depth to ground water < 50'
Wellhead Protection Area > 1000'
Distance to surface water body > 1000'

For sites with a Total Ranking Score of 20, the Recommended Remedial Action Levels are:

Benzene 10 BTEX 50 TPH 100

Incident Description:

The area is the site of a tank battery. The oil tanks ran over due to oil transporters not picking up and hauling oil load. All fluid of the discharge event was contained within the bermed area. The 40 barrel crude oil spill affected an approximate 25' X 30' X 3" area.

Action Taken:

Immediately upon discovery, the source of the release was eliminated by shutting in the well. A vacuum truck was called to remove fluids. Approximately twenty barrels of crude oil were recovered.

Work Plan:

The visual contaminates of the impacted area were immediately excavated and removed to an approved NMOCD commercial disposal site. Soil samples will be obtained and sent to a third party laboratory to be analyzed for TPH and BTEX. A 48 hour advance notice will be given OCD to allow opportunity to witness the sample collection. If concentrations exceed Recommended Remedial Action Levels (RRALs), further delineation and evaluation will be required. If, however, concentrations are within the RRALs, the excavated area will be backfilled with clean, like material and Yates Petroleum Corporation will request closure approval from OCD per section IX of the Guidelines.

Thank you for your consideration to this work plan. And should you have questions or need additional information, please contact me at 505-748-4162 or sherryb@ypcnm.com.


Respectfully,

Sherry Bonham

Environmental Regulatory Agent



Denotes Spill Area





Merle State Unit 3

Sec. 14 T10S R34E

Lea County, NM

DISCHARGE DIAGRAM RELEASE DATE: 12/4/06

(Not to Scale)

