District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action														
						<b>OPERA</b>	ΓOR		X Initi	al Report		Final Report		
							Contact Jimmy D. Carlile							
Address 303 West Wall, Ste 1800 Midland, TX Telephone No. 432 687-1777														
Facility Name James O'Neill Facility Type Tank Battery														
Surface Own	ner Sta	ate		Mineral (	Owner	State Lease No.								
		5n(		•										
			-			OF RE			/XX / X *	T 6 .				
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from th	ne East	/West Line	County				
В	7	15S	35E											
		<u> </u>	La	titu da		Langitud	la			1				
LatitudeLongitude														
NATURE OF RELEASE WTR ≈ 50°														
Type of Relea		0il	tank			Volume of		1.5		Recovered	1	0		
Source of Rel	Date and Hour of Occurrence Date and Hour of Discovery  If YES, To Whom? 12/11/06 12/11/06													
Was Immedia	ne Nonce C		Yes [	No 🗓 Not R	eauired	11 1 1 1 1 1 1 1 1 1	wnom?		pm	192021	2/1 200	1/06		
							Iou <del>r</del>		Pm X	1815	_<<2:	5 pm		
	By Whom? Was a Watercourse Reached?							Date and Hour  If VES, Volume Impacting the Watercourse						
			Yes 🔯	{ No		If YES, Volume Impacting the Watercourse								
If a Watercou	If a Watercourse was Impacted, Describe Fully.*  Not applicable													
i a watereou	ise was iii	pacicu, Desci	ibe i uny.						12	~	至岛	\$1		
Not applicable														
1	мос арр	olicable							1,6			J. Order		
					er tra	eater ar	d forgot	to o	nen the	Varer le	50 W	hen he		
Pumper was working on the heater treater and forgot to open the water leg when he was through with his work. All produced fluid went to the oil tank and floated														
15 BO our the thief hatch.														
					-1-1-									
Describe Area Affected and Cleanup Action Taken.*  All fluids were contained inside the diked area. A mixture of fertilizer and Oil														
				into the s				. mlxtt	ire or i	ertiize	r ai	10 011		
	Galui	MITT DE	mixed	Into the s	OII a	ind wate	red III.							
				is true and comp										
				nd/or file certain										
	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
				tance of a C-141										
federal, state,	or local lav	ws and/or regu	ılations.									<u></u>		
							OIL CONSERVATION DIVISION							
Signature:	Signature: Human allee							۳.	_					
						Approved by	District Supe	(Pas F146 TVISUT:	(C)	0				
Printed Name	: J1	mnly D. C	arlile	<u> </u>					- A	Miss	Arrier.			
Title:	Re	gulatory	Affai	rs Coor.		Approval Da	te: 5.29	. 01	Expiration	Date: 8-7	·a . i	20		
							3.0(			1				
E-mail Address: jimmyc@forl.com							f Approval:			Attached	П			
Date: 12/12/06 Phone: 432 687-1777														
Attach Additional Sheets If Nagassany							SUBMITTAL OF FINAL CHI							
A A	A .	- 04	y 	ما من	uwznt	ATION	134 -	001	+:	202				
hill-	ta -1	1/HCO2	1512	) 1 OC						KHI	7/	272		
quiu		Open	2101	35009						( ) 1	,	. —		
/)Mad	but -	DIVICO	ハノネ	706 27										
Sailty-FACO15135017 Sinadry-nPACO15135079 application-pPACO715135157														
aggini		٢												