
TEXLAND PETROLEUM, L.L.C. STATE 1-29 (GRIMES 28) Unit D, Sect. 29, T. 18 S., R. 38 E.

GPS: 32 42' 49" N 103 10' 00" W

CLOSURE

Prepared by Eddie Seay Consulting November 2005



NMOCD Environmental ATTN: Larry Johnson 1625 N. French Drive Hobbs, NM 88240

RE: Texland Petroleum

State 1-29 Grimes Battery Fire

Mr. Johnson:

Texland has completed the excavation phase of this remediation and testing. We are within guidelines for closing and would like to backfill with clean soil, level, contour and seed.

Texland excavated approximately 1158 cu. yds. of oily dirt and hauled it to CRI Disposal, an OCD approved facility. The clean soil will come from a site just West of Lovington.

Whenever we get approval, we will backfill as approved and send a final report.

Find enclosed photos, analytical and map of site. If you have any questions, please call.

Sincerely,

Eddie W. Seay, Agent Eddie Seay Consulting

601 W. Illinois Hobbs, NM 88242

(505)392-2236

seay04@leaco.net

SEP-15-2006 11:48 From: FEXLAND

District I 1623 N. French Dr., Hubbs, NM 88240 District II 1301 W. Grand Avenus, Artesia, NM 88210 District III 1000 Rio Bruzos Roed, Artec, NM 87410 Dismict IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

81 79001294

Oil Conservation Division 1220 South St. Francis Dr. Santa Pe NM 97505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

						, tam 6/2						
			Rele	ease Notific	ation	and Co	rrective A	ction				
						OPERA:			Initi:	il Report		Final Report
Name of Co	ompany T	exland E	etrol	eum-Hobbs I	ic i	Contact V:	ickie Smit	h				
Address 7	77 Main	St. Ste	3200	Fort Wort	<u>h. r</u>	iclephone l facility Typ				······································		
1.9CHITA MA	me Stat	e 1-29 F	white.c	y (\$5 & 6)								
Surface Ow	ner .			Mineral C	Whet	State of	of New Mex	i∞	Loase ?	io. B-22	77-1	
				LOCA		OF RE						
Unit Letter	Section	Township	Range	Feet from the	North	South Line	Feet from the	East/W	est Line	County		
0	29	18S	38E	approx 330)	South	2218	Ea	st	Lea		
<u></u>			L	titude		Longitud	le		,			
				·		OF REL						
Type of Rele	and Oi	l and wt	r	INAI	UKE		Release 242.	80	Volume I	Lecovered	0 80	· · · · · · · · · · · · · · · · · · ·
Source of Re						Date and I	lour of Occurrence	36	Date and	Hour of Dis	covery	6:00 am
Was Immedi		Given?	Yes [No Not Re	quired	ocp,	Whom? 5:0 (Hobbs	00 am	8/217	06		8/21/06
		Jackson				Date and I		am 8	/21/06			
Way u Water	rcourse Rea	chod?	Yes [No No		IF YES, V	olume Impacting t	me wate	roourse.			
If a Wateroo	urse was lin	pacted, Descr	be Fully.	+		 	***************************************	·· ······				
Describe Ca	use of Prob	lem and Reme	dial Actio	n Taken,*								
1				using tanks	+0	artah fi	*					
		ent was			. ω ι	JUL 21	14.C					
l .	•									· 		
1		and Cleanup						_		_		_
				surrounding and Eddie							up :	foam.
I hereby corr	ify that the	information <u>u</u>	iven ubov	e is true and comp	lete to ti	te best of my	knowledge and u	nderstan	d that pur	uani w NM	OCD n	ules und
regulations	ll operators	are required to	o report e	nd/or file certain r ce of a C-141 repo	elease n	otifications a	nd perform correct	tive soti	ons for rel	eases which	muy cr	ndunger
should their	operations l	have failed to	doquatel	y investigate and n	rmediate	s contaminati	on that pose a thr	cat to gr	ound water	, KUTTHOR W	ster, hu	man health
or the environ	nment. In t	udition, NMC	XCD acce	ptanos of a C-141	report d	veiler Jon kou	e the operator of	reaponai!	bility for co	ompliance v	vith any	other .
toderat, state	, or local is	ws and/or reg	BBC10113.	· · · · · · · · · · · · · · · · · · ·			OIL CON	SERV	ATION	DIVISIO	ואו	
N!	100	Ekië.	ς	Cal			<u> </u>	<u> </u>			<u></u>	
Signature:		E N. LO.	ma			A renewant has	District Supervis	e e e e e e e e e e e e e e e e e e e				
Printed Nam	e: Vic	kie Smit	<u>h</u>				- 1-2 tot Oakst 110	 '				•
Title:	Pro	duction 2	Analys	st		Approval Da	e:	E	xpiration l	Date:		
E-mail Addr	ess: VSM	ith@texp	etro.c	om	(Conditions of	Approval:			Attached		
Date: 8/	22/06		Phone	: 817-336-2	751	_					_	

* Attach Additional Shoets If Necessary



PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR EDDIE SEAY CONSULTING ATTN: EDDIE SEAY 601 W. ILLINOIS HOBBS, NM 88242 FAX TO: (505) 392-6949

Receiving Date: 11/15/06 Reporting Date: 11/16/06

Project Owner: TEXLAND PET.

Project Name: TEXLAND ST. 29 BATTERY

Project Location: HOBBS, NM

Sampling Date: 11/15/06

Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: NF Analyzed By: BC/AB

	GRO	DRO	
	$(C_{6}-C_{10})$	(>C ₁₀ -C ₂₈)	CI*
LAB NUMBER SAMPLE ID	(mg/Kg)	(mg/Kg)	(mg/Kg)

ANALYSIS DATE	11/15/06	11/15/06	11/15/06
H11801-1 ST. 29 - 1	<10.0	<10.0	96
H11801-2 ST. 29 - 2	<10.0	<10.0	64
H11801-3 ST. 29 - 3	<10.0	<10.0	96
H11801-4 ST. 29 - 4	<10.0	<10.0	64
Quality Control	767	765	500
True Value QC	800	800	500
% Recovery	95.8	95.7	100
Relative Percent Difference	1.0	1.3	4.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl⁻: Std. Methods 4500-Cl⁻B *Analyses performed on 1:4 w:v aqueous extracts.

Chemist

Date


RDINAL LABORATORIES, INC. 2111 Beechwood, Abilene, TX 79803

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Condition Character of Conditions of Character of Condition Character of Character	で で で で で で で で で で で で で で
	Addison

Sampler - UPS - Bus - Other:

Cardinal cannot accept verbal changes. Please tax written changes to \$15-673-7020.













, ,



