

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Kenneth N. Andersen
Address	4001 Penbrook, Odessa, TX 79762-5917	Telephone No.	505.391.3158
Facility Name	MCA Unit Battery # 2	Facility Type	Oil and Gas

Surface Owner	BLM	Mineral Owner	BLM	Lease No	LC - 057210
---------------	-----	---------------	-----	----------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	28	17S	32E					Lea Co.

100'

Latitude 32.81194N Longitude -103.77518W

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water	23 bbl (0 oil, 23 water)	(0 oil, 0 water)
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
MCA Unit Battery # 2 4" produced water trunk line.	07/06/2006 0530hrs	07/06/2006 0945hrs
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A dresser sleeve failed due to corrosion, age, & fatigue on the produced water trunk line. The site will be delineated & a remediation plan will be submitted to the NMOCD for approval.

Describe Area Affected and Cleanup Action Taken.*

100'X15' & 755'X3.5' of damp sandy pasture with no fluid recovered. However a vacuum truck was used to empty the 4" trunk line. The dresser sleeve was replaced with a flanged fiberglass spool.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	ACCEPTED ENVIRONMENTAL	
Title: HSER PSM Lead	Approved by District Supervisor: <i>[Signature]</i>	
E-mail Address: ken.n.andersen@conocophillips.com	Approval Date: 6-27-07	Expiration Date: 9-27-07
Date: 07/08/2006 Phone: 505.391.3158	Conditions of Approval:	Attached <input type="checkbox"/>
	SUBMITTAL OF FINAL C-141	

- Attach Additional Sheets If Necessary

facility - PAC0619939966
incident - PAC0619940049
application - PAC0619940284
SUPPORTING DATA OF
REMOVAL OF ALL CONTAMINATED
SOIL TO DISPOSAL BY R# 959