

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Co., LP	Contact: Jennifer Van Curen	
Address: PO Box 250; Artesia, NM 88211	Telephone No. 505-748-0160	
Facility Name Lea R State NCT A 1	Facility Type Well API # 30 025 00370 0000	
Surface Owner 7	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section 21	Township 16S	Range 32E	Feet from the 990	North/South Line North	Feet from the 660	East/West Line East	County Lea
2		Latitude		Longitude				

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 12 bbls	Volume Recovered: 0 bbls
Source of Release: Flow line	Date and Hour of Occurrence: <del>3-30-04</del> 11:30 AM 5/29/06	Date and Hour of Discovery: <del>3-30-04</del> 11:30 AM 5/29/06
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton (NMOCD) - OCD 5/29/06	
By Whom? Roger Hernandez: Foreman	Date and Hour: <del>3-30-04</del> 12:36 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Hole in flow line at road crossing (buried) going to production equipment due to corrosion. Visually inspected the rest of the line. Replaced portion with polyethylene pipe. Shut pumping unit down and shut well in.

Describe Area Affected and Cleanup Action Taken.\*

Area affected was a 60' by 30" strip down roadway. Replaced steel flow line with polyethylene pipe. Left area to aerate for a few days. Fertilized area with high nitrogen fertilizer. Back drag and treated affected area as needed

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jennifer Van Curen	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen	Approved by District Supervisor: E. W. Egan	
Title: Production Field Tech	Approval Date: 6-26-07	Expiration Date: —
E-mail Address: Jennifer.Vancuren@dv.com	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 7-11-06 Phone: 748-0160		

\* Attach Additional Sheets If Necessary

incident - n PAC0620135224  
application - p PAC0620135738

RP#968