


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 S. St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Rice Operating	Contact Tony Grieco
Address 122 W. Taylor St., Hobbs, NM 88240	Telephone No. (505) 393-9174
Facility Name: EME SWD I-1	Facility Type: Salt Water Gathering System

Surface Owner : State of New Mexico	Mineral Owner	Lease No.
-------------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter I	Section I	Township 20S	Range 36E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32° 36.076 N Longitude 103° 18.044 W

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 20 bbls	Volume Recovered 18 bbls
Source of Release Broken manifold on a temporary tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 6/15/07 8:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A manifold on a temporary tank leaked. The manifold was replaced as a permanent repair

WHAT ARE CHLORIDES ON SPICED
WTR ? ALWAYS INCLUDE THIS
ON SPILLS

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was immediately dispatched to remove the water to an approved disposal facility. The surface of the entire spill area was scraped as soon as the surface water was removed on 6/15/07 and the impacted soil hauled to an approved disposal facility.

SAMPLE RESULTS ?

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Tony Grieco	Approved by District Supervisor:	
Title: Environmental Tech	Approval Date: 6-29-07	Expiration Date: 9-10-07
E-mail Address: tgrieco@riceswd.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 15, 2007 Phone: (505) 393-9174	SUBMITTER OF FINAL C-141	

* Attach Additional Sheets If Necessary

w/ DOCUMENTATION

RA# 7461