

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <i>Marbob Energy Corp.</i>	Contact <i>Cliff Brunson - BBC International</i>
Address <i>P.O. Box 227 Artesia, NM 88211</i>	Telephone No. <i>505-397-6388</i>
Facility Name <i>Scratch State Com #1.</i>	Facility Type <i>oil well / Drilling Pit</i>
Surface Owner <i>State of N.M.</i>	Mineral Owner <i>State</i>
Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>24</i>	<i>18S</i>	<i>33E</i>	<i>1980</i>	<i>North</i>	<i>660</i>	<i>WEST</i>	<i>LEA.</i>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ API# *30025369960000*

**NATURE OF RELEASE**

Type of Release <i>Pit Liner</i>	Volume of Release <i>Unknown</i>	Volume Recovered <i>None</i>
Source of Release <i>Pit</i>	Date and Hour of Occurrence <i>?</i>	Date and Hour of Discovery <i>8/20/07</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Daniel Sanchez - phone; Wayne Price - email</i>	
By Whom? <i>Rand French &amp; Cliff Brunson</i>	Date and Hour <i>8/20/07 - 2:07 pm</i>	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>UNKNOWN</i>	

If a Watercourse was Impacted, Describe Fully.\*

*Do not know the extent of impacts at this time*


Describe Cause of Problem and Remedial Action Taken.\*

*Compromised Pit - was in the process of a dig-n-haul, along with delineating chlorides. Forty feet below ground surface wet soils and water was encountered.*

Describe Area Affected and Cleanup Action Taken.\*

*Unknown at this time. Most of the Pit material has been removed. The West side of Pit was free of chlorides @ 12' feet.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Rand French</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Rand French</i>	Approved by District Supervisor: <i>[Signature]</i>	
Title: <i>Wildlife Biologist</i>	Approval Date: <i>8.29.07</i>	Expiration Date: <i>9.17.07</i>
E-mail Address: <i>wildlife@marbob.com</i>	Conditions of Approval: <i>SUBMIT DATA &amp; PLAN BY</i>	
Date: <i>8/24/07</i> Phone: <i>748-3303</i>	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*AP# 1536*