

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 <sup>TH</sup> STREET	Telephone No. 505.748.1471	
Facility Name ROSEMARY BOOSTER	API Number	Facility Type PIPELINE
Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No

**LOCATION OF RELEASE**

Unit Letter L	Section 6	Township 22S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release PRODUCED WATER	Volume of Release 100 B/PW and 1/2 B/O	Volume Recovered 10 Barrels PW/O
Source of Release PIPELINE	Date and Hour of Occurrence 08/07/07 5:00 AM	Date and Hour of Discovery 08/07/07 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD VOICEMAIL	
By Whom? ROBERT ASHER	Date and Hour 8/7/07 2:38 PM AND FOLLOW UP EMAIL 8/7/07 2:48 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

WTK  
200

DATE RECD ?

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
ELECTRICAL PROBLEM CAUSED CONNECTIONS ON WATER LINE TO MELT. TURNED PUMP OFF AND SHUT VALVE ON WATER LINE. REPAIRS MADE TO LINE.  
**CHLORIDE CONTENT (WATER) SPILLED**

Describe Area Affected and Cleanup Action Taken.\*  
APPROXIMATELY 75' X 20' AREA AFFECTED. CALLED IN VACUUM TRUCK. VACUUMED STANDING FLUIDS. EXCAVATED AND HAULED IMPACTED MATERIALS TO DISPOSAL FACILITY.  
**How WAS 'IMPACTED MATERIAL' DETERMINED ?**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Sherry Bonham		
Title: Environmental Regulatory Agent	Approved by District Supervisor:	<b>ENVIRONMENTAL ENGINEER</b>
E-mail Address: sherryb@ypnm.com	Approval Date: 9-11-07	Expiration Date: 10-12-07
Date: August 10, 2007	Phone: 505.748.1471	Conditions of Approval:
		Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

①

RP# 1527