

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company CHEVRON USA INC.	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1237 (office), 505-390-7165 (cell)
Facility Name- Eunice King #28	Facility Type - Oil well

Surface Owner- Chevron USA, INC	Mineral Owner - Chevron USA	Lease No.
---------------------------------	-----------------------------	-----------

LOCATION OF RELEASE API # 3002536739

Unit Letter B	Section 28	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release-OIL AND PRODUCED WATER	Volume of Release ½ BO, 5 BW	Volume Recovered- 4 ½ bbl total fluid
Source of Release- Hercules Stuffing Box	Date and Hour of Occurrence- 09/13/07 8:00 am	Date and Hour of Discovery 09/13/07 8:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 9/13/07 @ 4:30 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Cooler weather at night caused stuffing box to leak spilling fluid out around pumping unit base. Called out vacuum truck and picked up standing fluid on location.

Describe Area Affected and Cleanup Action Taken.* Had an area on both sides of pumping unit that measured 60' X 4' and 50' X 4'. Picked up standing fluid and took to third party disposal and back drag location around pumping unit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION 	
Printed Name: Larry Williams	Approved by District Supervisor: ENVIRONMENTAL ENGINEER	
Title: Production Representative	Approval Date: 9-18-07	Expiration Date: —
E-mail Address: lcwl@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/14/07	Phone: 505-394-1237	

* Attach Additional Sheets If Necessary

RP# 1561